

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 12 Oct 2020

Preliminary Advice

Insured Vehicle No	: GBH4535G		
TP Vehicle No	: SKW5607R	Accident Date	: 30/09/2020
Make	: MERCEDES-BENZ E250	Assignment Date	: 07/10/2020
Date of Inspection	: 06/10/2020	Est. Duration of Repair	: 3
Inspection At	: POON SIANG SEOW (HQ) 160 SIN MING DRIVE, #05-13 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,335.00
Revised Amount	:S\$	8,498.90
Check Items (Estimated)	:S\$	511.50
Total	:S\$	9,010.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted without "prejudice" basis.