

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
SOMPO INSURANCE SINGAPORE PL			Ref : CS/SMO20010761/QUvf3e2		
50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Date: 10-12-2020 Code: SMO		
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBJ 226P	Veh. Inspected	SML 6548E	
	Policy No.	D19MTHCVE000176	Coverage (\$)	0.00	
	Claim No.	CMTD2002920/IJH	Excess (\$)	0.00	
	Assign From	GRACE TEO	Assign Date	06/10/2020	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA NOAH HYBRID	c.c	1797	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	ZWR800379863	Colour	BLACK	
	Odometer	150942	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	ARIVO	6 mm	
	L/H Front Tyre	195/65 R15	ARIVO	6 mm	
	R/H Rear Tyre	195/65 R15	ARIVO	6 mm	
	L/H Rear Tyre	195/65 R15	ARIVO	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	05/10/2020	Inspection Date	07/10/2020	
	Survey held at	60 JALAN LAM HUAT, CARROS CENTRE #05-68			
	Repairer MY CAR CONSULTANT PTE LTD				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. 3)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days				