



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS3/LPC20007278/Gtf3e2-1

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 09-10-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 7812H	Veh. Inspected	SLW 2714Y
Policy No.		Coverage (\$)	0.00
Claim No.	20/20/20/VC05/023458	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	06/10/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MR053REH604576227	Colour	BROWN
Odometer	40077	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	YOKOHAMA	6 mm
L/H Front Tyre	215/45 R17	YOKOHAMA	6 mm
R/H Rear Tyre	215/45 R17	YOKOHAMA	6 mm
L/H Rear Tyre	215/45 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/07/2020	Inspection Date	14/07/2020
Survey held at	LIM MOTOR PTE LTD 160 SIN MING DRIVE #05-20 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------