



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date:

Vehicle:

Make / Model:

Chassis No:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

6/10/2020

Acknowledged by Repairer

SMR3784C

TOYOTA PRIUS

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER <i>/ det.</i>	1	\$ 698.00	\$ 698.00
2	REAR BUMPER LOWER <i>X / SCR</i>	1	\$ 412.00	\$ 412.00
3	REAR BUMPER SIDE RETAINER <i>X SVC</i>	2	\$ 112.00	\$ 224.00
4	TAILAMP LH <i>X SVC</i>	1	\$ 489.00	\$ 489.00
5	REAR FENDER LH <i>/ DP</i>	1	\$ 798.00	\$ 798.00
6	REAR FENDER COWLING LH <i>X SVC</i>	1	\$ 159.00	\$ 159.00
7	REAR FENDER QUARTER GLASS MLDG LH <i>/ Nec</i>	1	\$ 189.00	\$ 189.00
8	ROCKER PANEL GARNISH LH <i>/ det</i>	1	\$ 798.00	\$ 798.00
9	REAR DOOR LH <i>/ DP</i>	1	\$ 1,214.00	\$ 1,214.00
10	REAR OUTER MOULDING LH <i>X SVC</i>	1	\$ 124.00	\$ 124.00
11	REAR DOOR WEATHERSTRIP LH <i>X SVC</i>	1	\$ 198.00	\$ 198.00
12	REAR KNUCKLE ARM LH <i>X SVC</i>	1	\$ 487.00	\$ 487.00
13	REAR KNUCKLE ARM BEARING LH <i>X / Jam</i>	1	\$ 148.00	\$ 148.00
14	REAR AXLE <i>X SVC</i>	1	\$ 1,985.00	\$ 1,985.00
15	REAR SHOCK ABSORBER LH <i>X SVC</i>	1	\$ 418.50	\$ 418.50
				\$ 8,341.50
			Less 25%	\$ 2,085.38
			Total	\$ 6,256.13
S/Nett items:				
1	REAR BUMPER CLIPS SET <i>/ NEC</i>	1	\$ 50.00	\$ 50.00
2	REAR FENDER COWLING CLIPS SET <i>X SVC</i>	1	\$ 50.00	\$ 50.00
3	REAR SPORTS RIM RH <i>/ SCR</i>	1	\$ 800.00	\$ 800.00
4	REAR TYRE RH <i>X SVC</i>	1	\$ 250.00	\$ 250.00
5	REAR STICKER SET <i>X SVC</i>	1	\$ 300.00	\$ 300.00
6	BRAKE FLUID <i>X SVC</i>	1	\$ 50.00	\$ 50.00
				\$ 1,500.00
Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	REMOVE AND TRANSFER REVERSE SENSOR	1	\$ 120.00	\$ 120.00
3	CONDUCT FULL WHEEL ALIGNMENT	1	\$ 120.00	\$ 120.00
4	REMOVE AND REFIT REAR UNDERCARRIAGE	1	\$ 400.00	\$ 400.00
5	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00
6	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
7	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,000.00	\$ 1,000.00
8	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,000.00	\$ 1,000.00
				\$ 3,070.00
Repair day - 4 days			Parts Replacement Amount	\$ 7,756.13
L/S			Total Amount for Labour	\$ 3,070.00

After paint photo
Sun Pin (LH/LH)
07/10/2020
TP with prejudice

Resurvey
06/10/2020

L/S
\$4,200
4 days

3,061.50
630
1,580
5,271.50
- 20%
4,217.20