

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SHB4447M

02/10/20

MAKE :

MODEL HYU- I40

CHIANG/ NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER X R			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH X NN		\$35.60	\$71.20
10	REAR BUMPER CLIPS X NN		\$2.20	\$22.00
1	REAR BUMPER REINFORCEMENT X NN			\$428.40
1	REAR BUMPER UNDER COVER X NN			\$228.00
				\$1,855.60
	20.00%			\$371.12
	DISCOUNTED TOTAL			\$1,484.48
1	REVERSE SENSOR X NN 10.00 %			\$135.70
				\$122.13
	Labour Charge			
	Panel Beating			\$480.00
	Spray Painting Charge			\$300.00
	Remove/refix reverse sensor			\$60.00
	Tuff Kote			\$90.00
	TOTAL LABOUR			\$930.00
	ESTIMATE TOTAL			\$1,536.61
				2,536.61#
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Steve (LKK) WTL MFL

6/10/20

2 days

L/S (Part by Part if labour only)

By AL SPY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: