

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 08 Oct 2020

Preliminary Advice

Vehicle No	: XE3905J	Accident Date	: 30/09/2020
Make	: MAN TGS 35.360	Policy No.	: MU013224
Assignment Date	: 06/10/2020	Excess	: S\$4,500.00
Date of Inspection	: 07/10/2020	Est. Duration of Repair	:
Inspection At	: ST Engineering Land Systems Ltd (HQ) 31 Corporation Road Singapore 649825		

Point of Impact / General Description of Damages

Pending investigation & fire report.

Repairer's Estimate (Gross)	:S\$	PENDING ESTIMATE
Revised Amount	:S\$	PENDING ESTIMATE
Check Items (Estimated)	:S\$	PENDING ESTIMATE
Total	:S\$	PENDING ESTIMATE
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	100,000.00 (EXCLUDE CRANE)
COE / PARF Rebate	:S\$	30,291.00
Salvage Value	:S\$	
Margin for Repair	:S\$	69,709.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Pending estimate from repairer.