

Lee Kuan Hwa Motor Service (Co.Reg.No:36463500B)20 Gul Crescent
Singapore 629529

Tel: 62699192 Fax: 62692239 Email: kuanhwa@singnet.com.sg

(SUPPLEMENTARY)**INSURER:** **Tokio Marine Insurance Singapore Ltd (HQ)****PARTICULARS OF CLAIM**

Claim Type: OD (OWN DAMAGE)

Policy No: MU013224

Vehicle Reg. No.: **XE3905J**

Driver Age/Info: 56 / MALE

TP Injury Involved? NO

Insured/Claimant: TANGLIN CORPORATION PTE LTD
Driver: YONG CHEE FUI GREGORY

Ref. No:

Date of Loss: 30/09/2020

Driveable? YES

Party At Fault: UNKNOWN

Third Party
Involved? NOMake/Model: MAN TGS 35.360, 10.5 D 8X4 BB
(M)

Vehicle Colour: WHITE

Engine No: 50546182524618

Odometer: 0 KM

Vehicle Reg. Date: 26/12/2017

Gen Condition: GOOD

Chassis No: WMA37SZZ0HM729564

Paint Type:

Total Loss? **NO**Est. Duration of Repair
(day) 10Description of
Accident/Loss

REFER TO ATTACHED STATEMENT

Present Location:

LEE KUAN HWA MOTOR SERVICE (GUL CRESCENT)

COST OF CLAIMS

	Amount
Parts	2,518.49
Miscellaneous Items	160.27 158.77
Labour	0.00
Paintwork Labour	0.00
Towing	0.00

Nett Amount (\$) 2,678.76 ~~2,077.26~~**+ Previous Estimates (\$)** 13,542.44 ~~43,543.21~~**Claim Total (\$)** 16,221.20 ~~16,220.47~~

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Source:

Parts: N/A (Last Synchronised: 06 Nov 2020)
 Labour: Repairer's MAN TGS 35.360 10.5 D 8X4 BB (M) (Model not available in database)
 Print Code: Lee Kuan Hwa Motor Service/XE3905J/06/11/2020 14:22 (Price-denominated Standard List)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*SNAP NUT	0.00	0.00	*18.24 F/NEC
2	1		*CONTACT BUSH	0.00	0.00	*63.90 F/DEF
3	1		*BLADE TERMINAL	0.00	0.00	*13.20 F/BNT
4	1		*UNLOCKING TOOL	0.00	0.00	*118.32 F/NEC
5	1		*CRIMPING PLIERS HEAD	0.00	0.00	*880.18 F/NEC
6	1		*CONNECTOR HOUSING	0.00	0.00	*14.30 F
7	1		*CONNECTOR HOUSING	0.00	0.00	*14.30 F
8	1		*CABLE HARNESS	0.00	0.00	*95.04 F
9	1		*CABLE HARNESS OWER TAKEOFF	0.00	0.00	*115.60 F
10	1		*CABLE HARNESS CAN DATA BUS	0.00	0.00	*70.24 F
11	1		*CABLE HARNESS EDC7	0.00	0.00	*96.14 F
12	1		*CABLE HARNESS ENGINE	0.00	0.00	*200.38 F
13	1		*CABLE HARNESS RETARDER	0.00	0.00	*27.66 F
14	1		*TOOL SUPPORT CO DRIVE SIDE	0.00	0.00	*28.06 F
15	1		*MOLDINGCO DRIVER SIDE	0.00	0.00	*155.02 F
16	1		*CAB FILTER	0.00	0.00	*95.70 F
17	1		*AIR DUCT RIGHT	0.00	0.00	*23.58 F
18	1		*AIR DUCT	0.00	0.00	*12.98 F
19	1		*AIR DUCT	0.00	0.00	*18.00 F
20	1		*AIR DUCT	0.00	0.00	*26.18 F
21	1		*AIR DUCT OUTER	0.00	0.00	*33.54 F
22	1		*AIR DUCT	0.00	0.00	*12.68 F
23	1		*HEATER FLAP	0.00	0.00	*126.96 F
24	1		*LEVER	0.00	0.00	*7.92 F
25	1		*CABLE HARNESS	0.00	0.00	*21.42 F

F=Franchise part.

Sub Total (\$\$) 2,289.54
 + Margin on L,N Items 10.00% (\$\$) 228.95
Total Parts (\$\$) 2,518.49

Lee Kuan Hwa Motor Service/XE3905J/06/11/2020 14:22. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Miscellaneous Items

Particulars		Amount
<u>Miscellaneous Items</u>		
1	7% GST FROM SUPPLIER	158.77
Sub Total (S\$)		158.77
		160.27

Estimates on Labour

There are no labour items selected.

Lee Kuan Hwa Motor Service/XE3905J/06/11/2020 14:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >