

SJE :	_____	Vehicle Nos :	SMC 4484 R
Date of Survey :	_____	Model :	Hyundai Accent
Date of ReSurvey:	_____	Year :	_____
Contacts :	_____	Chassis No :	_____
	After-Paint:		

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount:	_____	Working Day:	_____
----------------	-------	---------------------	-------

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Rear bumper	1	\$ 958.00	\$ 789.89 958.00	cut ✓
2	Rear bumper retainer	2	\$ 105.60	\$ ✓ 211.20	NEC ✓
3	Rear fender LH	1	\$ 1,254.00	\$ ✓ 1,254.00	DD ✓
4	Rear fender inner trim board LH	1	\$ 254.00	\$ 254.00	NDX
5	Rear fender inner cowling LH	1	\$ 103.20	\$ 103.20	NDX
6	Rear air vents LH	1	\$ 66.20	\$ 66.20	NDX
7	Rear windscreen moulding	1	\$ 182.36	\$ ✓ 182.36	NEC ✓
8	Taillamp LH	1	\$ 786.30	\$ 697.80 786.30	BR ✓
9	Taillamp lower brakel LH	1	\$ 87.60	\$ 87.60	NSX
10	Rear shock absorber LH	1	\$ 653.20	\$ 653.20	ND
11	Rear axle	1	\$ 890.00	\$ 890.00	X
12	Rear wheel hub with bearing LH	1	\$ 483.50	\$ 454.00 483.50	IM ✓
Parts Sub Total :				\$ 3,589.25 5,929.56	
Discount 20% :				\$ 717.85 1,185.91	
PARTS TOTAL :				\$ 2,871.40 4,743.65	

Nos.	SPECIAL NETT ITEMS	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NNX
2	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00	NEC ✓
3	Rear fender sealant	1	\$ 100.00	\$ 40.00 100.00	NEC ✓
4	Rear fender inner trim board clips	1	\$ 50.00	\$ 50.00	NNX
5	Rear fender inner cowling clips	1	\$ 50.00	\$ 50.00	NNX
6	Rear windscreen sealant	1	\$ 100.00	\$ 50.00 100.00	NEC ✓
7	Rear windscreen inner seal	1	\$ 60.00	\$ 60.00	NNX
8	Rear windscreen primer & cleaner	1	\$ 80.00	\$ 80.00	NNX
9	Taillamp seal	1	\$ 60.00	\$ 30.00 60.00	NEC ✓
10	Taillamp clips	1	\$ 50.00	\$ 50.00	NSX
11	Rear rim LH	1	\$ 650.00	\$ 400.00 650.00	AT ✓
12	Rear tyre LH	1	\$ 350.00	\$ 350.00	NDX
SPECIAL NETT TOTAL :				\$ 550.00 1,680.00	

Nos.	LABOUR	S\$	
1	R&R reverse sensor	\$ 60.00	150.00 ✓
2	R&R rear windscreen	\$ 120.00	250.00 ✓
3	R&R fuel tank pipe	\$ 70.00	150.00 ✓
4	R&R rear undercarriage parts	\$ 150.00	250.00 ✓
5	R&R rear tyre and balancing	\$ 30.00	80.00 ✓
6	Wheel alignment	\$ 60.00	120.00 ✓
7	Check wiring	\$ 30.00	100.00 ✓
8	Upholstery	\$ 100.00	300.00 ✓
9	Panel beat	\$ 600.00	1,000.00 ✓
10	Rust proofing	\$ 60.00	200.00 ✓
11	Spray paint	\$ 600.00	1,000.00 ✓
LABOUR TOTAL :		\$ 1,880.00	3,600.00

Survey 7/10/2020
 Resurvey 8/10/2020
 T&C 1400 hrs
 T&C 1430 hrs

PARTS TOTAL : \$ 4,743.65
 SPECIAL NETT TOTAL : \$ 1,680.00
 LABOUR TOTAL : \$ 3,600.00
 GRAND TOTAL : \$ 10,023.65

Lump sum repair
 Repair days 6

PARTS 2,871.40
 S/N 550.00
 LABOUR 1,880.00
 5,301.40
 @ 20% 1,060.28
 4,241.12

45 4,200/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

T&C
 28/10/2020