



TRANS EUROKARS PTE LTD



FINALIZATION COST OF REPAIRS

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Thoe Teck Beng ADDRESS : 669d Jurong West Street 64 #14-58 Singapore 644669 TEL : Mr Thoe Teck Beng		WIP : 20073 EXCESS : DATE: 5-Oct-20		
VEH NO :	SJR6222Z	DATE IN :		CONTACT PERSON :	Jess 63957874	
CHASSIS NO :	JM6CC1071H0111224	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM	
MODEL :	BIANTE	DATE REG.:	17-Jul-17	POLICY NO. :		
NATURE OF WORKS						
Parts Description						
NO	QTY			REVISED	PRICES	
1	REAR BUMPER	1	MC275-50-221FBB	1,170.50	1,170.50	
2	GROMMET, REAR BUMPER	2	MBP4K-50-ES1	9.40	9.40	
3	PIN LOCATOR, REAR BUMPER	2	MGJ6B-50-1K5	8.40	8.40	
4	GROMMET, REAR BUMPER	2	MB01W-51-142B	6.40	6.40	
5	RIVET, REAR BUMPER	2	MA001-50-7C1	7.60	7.60	
6	FASTENER, REAR BUMPER	2	MGD7A-50-EA1	6.40	6.40	
7	STRIPE LHS, REAR BUMPER	1	MC467-50-888	86.00	86.00	
8	STRIPE RHS, REAR BUMPER	1	MC467-50-878	86.00	86.00	
9	STRIPE CENTER, REAR BUMPER	1	MC467-50-879	130.10	130.10	
10	REFLECTOR RHS, REAR BUMPER	1	MC273-51-5L0A	-	124.50	
11	RETAINER RHS	1	MC273-50-2H1C	-	48.80	
12	TAPE PROTECTOR, REAR BUMPER	2	MG043-62-864A	7.00	7.00	
13	TAILGATE	1	MC2Y3-62-02XF	1,699.70	1,699.70	
14	VALVE ONEWAY, TAILGATE	2	MGHP9-58-867	24.00	24.00	
15	FINISHER, TAILGATE	1	MC273-50-850L	2,018.60	2,018.60	
16	FASTENER, TAILGATE	3	MEG21-51-146	18.60	18.60	
17	ORNAMENT, SKYACTIV	1	MC603-51-771A	117.10	117.10	
18	FASTENER, REAR WINDSCREEN	1	MD204-50-896A	2.80	2.80	
19	SPACER, REAR WINDSCREEN	5	MGJ6A-50-897	64.00	64.00	
20	FASTENER, REAR WINDSCREEN	2	MC273-50-896	16.40	16.40	
21	TAILLAMP RHS	1	MC273-51-150F	1,117.20	1,117.20	
TOTAL PARTS				6,596.20	6,769.50	
TOTAL PARTS COST				6,596.20	6,769.50	
Labour Description						
1	MZ-BR-REAR04	TO REPLACE REAR BUMPER AND TAILGATE.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			1,650.00	1,980.00
2	MZ-SP-SREAR4	TO RESPRAY REAR BUMPER AND TAILGATE.			1,260.00	1,890.00

3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	560.00	560.00	
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	120.00	120.00	
5	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.	-	330.00	
6	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.(WITH REVERSE SENSOR)	330.00	660.00	
7	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.(WITH REVERSE CAMERA)	330.00	660.00	
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150.00	250.00	
9	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	-	250.00	
10	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180.00	350.00	
11	MZ-BR-SUNDRI	SUNDRIES.	20.00	100.00	
			TOTAL LABOUR	4,600.00	7,150.00
			TOTAL PARTS	6,596.20	6,769.50
			TOTAL	11,196.20	13,919.50
			LESS EXCESS	-	-
			TOTAL AFTER EXCESS	11,196.20	
			GST 7%	783.73	-
			GRAND TOTAL	11,979.93	-

REMARKS:

6 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)