



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD
8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:CYNTHIA

Ref: CC4/ASM20010835/Abs3q2
Date: 14/05/2021
Code: ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 8721U	Veh. Inspected	SJH 2897E
Policy No.	P2379688	Coverage (\$)	0.00
Claim No.	S0M02UT1	Excess (\$)	0.00
Assign From		Assign Date	08/10/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053HY9305074577	Colour	PURPLE
Odometer	212004 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	TOURADOR	6 mm
L/H Front Tyre	195/55 R15	TOURADOR	6 mm
R/H Rear Tyre	195/55 R15	TOURADOR	6 mm
L/H Rear Tyre	195/55 R15	TOURADOR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/09/2020	Inspection Date	13/10/2020
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**