

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

WDA

Name : Neo Ah Yong

Accident Date : 19-Sep-20

Vehicle No : FX1181G

Vehicle Model : Hongshi
NF125MD

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
2	Fork inner tubes <i>Bul/tm</i>	\$ 280.00 ✓
2	Fork outer tubes <i>Bul/tm</i>	\$ 290.00 ✓
1	Fork under bracker <i>Bul</i>	\$ 185.00 ✓
1	Side mirror 1/11 <i>0/5 cut</i>	\$ 48.00 ✓
2	Front signals (1 set) <i>CR</i>	\$ 70.00 —
1	Headlamp assy <i>CR</i>	\$ 60.00 —
1	Meter assy <i>11</i>	\$ 360.00 X
1	Handle-bar <i>su</i>	\$ 80.00 X
1	Handle bar bracket <i>11</i>	\$ 95.00 X
1	Hand grip (1 set) <i>cut</i>	\$ 25.00 —
1	Brake lever <i>CR</i>	\$ 20.00 —
1	Front brake disc <i>11</i>	\$ 80.00 X
1	Front rim <i>11</i>	\$ 260.00 X
1	Front rim shaft <i>11</i>	\$ 35.00 X
1	Front footrest bracket <i>best</i>	\$ 55.00 ✓
1	Front footrest rubbers <i>toin</i>	\$ 56.00 ✓
1	Gear pedal <i>11</i>	\$ 40.00 X
1	Brake pedal <i>cut</i>	\$ 42.00 —
1	Rear footrest <i>cut</i>	\$ 38.00 —
1	Rear footrest bracket <i>11</i>	\$ 50.00 X
1	Exhaust assy <i>11</i>	\$ 425.00 X
1	Exhaust pipe cover <i>11</i>	\$ 310.00 X
1	Front fender <i>CR</i>	\$ 68.00 —
1	Front inner cover centre <i>CR</i>	\$ 45.00 —
1	<i>1/11</i> Rear fender <i>CR</i>	\$ 68.00 —
1	Rear swing arm <i>11</i>	\$ 220.00 X
1	Fairing assy (1 set) <i>CR</i>	\$ 485.00 —
1	Rear rim <i>cut</i>	\$ 290.00 ✓
1	Rear rim shaft <i>su</i>	\$ 40.00 X
1	Rear suspension (1 set) <i>11</i>	\$ 320.00 X

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Neo Ah Yong

Accident Date : 19-Sep-20

Vehicle No : FX1181G

Vehicle Model : Hongshi
NF125MD

Estimated Repair Costs

1	Chain adjust	set	\$	30.00	✓
1	Basket	cm	\$	30.00	✓
1	Side stand	ny	\$	40.00	X
1	Main stand	ny	\$	60.00	X
			\$	4,600.00	
			Less 10%	\$	460.00
			\$	4,140.00	

Special Nett Items

1	Number Plate (1 set)	set	\$	28.00	10
2	Fork oils	ner	\$	30.00	2
2	Fork oil seals	ner	\$	56.00	2
1	Steering cone bearing (1 set)	ner	\$	85.00	✓
1	Rear box	cm	\$	200.00	150
1	Rear box bracket	ny	\$	100.00	X
1	Sticker set	ner	\$	60.00	✓
1	E.R.P IU	R	\$	200.00	X
			\$	759.00	

S/No. Labour

1	To provide towing	\$	50.00	35
2	To check wiring and reset headlamp focusing	\$	ny 80.00	X
3	To provide labour	\$	420.00	300
		\$	550.00	

Grand Total

\$ 5,449.00

Dollars: Five Thousand Four Hundred and Forty-Nine only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultant's hence notify

only. Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by: Repairer

Signature:

2188
26925