



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

INDIA INTERNATIONAL INSURANCE PTE LTD 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Lam Khee Chong ADDRESS : 14 West Coast Grove Singapore 127825 TEL : 96960225		WIP : 20031 EXCESS : DATE: 2-Oct-20	
VEH NO :	SMT1284G	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6DJ2HAA01300395	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 2	DATE REG. :	27-Mar-20	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	REAR BUMPER	1	de✓	893.40	
2	BRACKET, CENTER	1	?	5.40	
3	STAY, REAR BUMPER	2	?	22.80	
4	RETAINER RHS	1	?	27.20	
5	GROMMET, REAR BUMPER	4	nel✓	10.80	
6	FASTENER, REAR BUMPER	7	nel✓	21.00	
7	CLIP, REAR BUMPER	4	nel✓	14.80	
8	TAPE PROTECTOR, REAR BUMPER	5	nel✓	23.50	
9	RETAINER CENTER RHS, SENSOR	1	nel✓	18.20	
10	SENSOR CENTER RHS, ULTRASONIC	1	nm✓	180.90	
11	REAR END PANEL	1	X	477.10	
12	GASKET LHS, TAILGATE	1	nel✓	54.30	
13	GASKET RHS, TAILGATE	1	nel✓	54.30	
14	MASCOT, REAR	1	X	61.20	
15	ORNAMENT, MAZDA 2	1	X	58.30	
16	ORNAMENT, SKYACTIV	1	X	68.00	
17	CAMERA-BACK MONITOR	1	?	846.00	
18	ANTENNA	1	?	111.10	
19	CLIP, ANTENNA	1	?	2.70	
20	LAMP, LICENSE	2	X	111.60	
21	UNDER COVER, REAR BUMPER	1	X	70.40	
22	FASTENER, UNDER COVER	4	X	12.00	
23	SILENCER	1	X	1,105.90	
24	GASKET, SILENCER	1	X	15.40	
TOTAL PARTS				4,266.30	
TOTAL PARTS COST				4,266.30	
Labour Description					

1	MZ-SP-SREAR1	TO RESPRAY REAR BUMPER AND REAR END PANEL.	660	2,970.00
2	MZ-SP-SREAR4	TO RESPRAY REAR BUMPER, REAR END PANEL AND TAILGATE.	630	2,520.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	NETT X	180.00
4	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	X	660.00
5	MZ-BR-REVSSEN	TO TRANSFER REVERSE SENSORS.	3 ✓	330.00
6	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	✓	330.00
7	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	NETT	70.00
8	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150.	250.00
9	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	X	250.00
10	MZ-BR-EXASSY	TO REMOVE & INSTALL REAR EXHAUST ASSY.	X	990.00
11	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	350.00
12	MZ-BR-SUNDRI	SUNDRIES.	20.	100.00

Taughlin 97475749
 WP 9/10/20 @ 320
 • 3 days
 Resurvey before paint
 Taughlin @ 1/10/20 W.H.

TOTAL LABOUR	-	9,000.00
TOTAL PARTS	-	4,266.30
TOTAL	-	13,266.30
LESS EXCESS	-	-
TOTAL AFTER EXCESS	-	-
GST 7%	-	-
GRAND TOTAL	-	-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR

TRANS EUROKARS PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE Page 2 of 2