



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI20010857/Asd3e2 Date: 21/12/2020	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SVJ 7534X		Veh. Inspected	SLG 4735H
Policy No.			Coverage (\$)	0.00
Claim No.	C10007499		Excess (\$)	0.00
Assign From	IVY RATILLA		Assign Date	08/10/2020
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 523I		c.c	2497
Engine No.	HIDDEN		Year of Reg.	2012
Chassis No.	WBAFP32040C865246		Colour	SILVER
Odometer	146810 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
	L/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
	R/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm
	L/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	03/10/2020	Inspection Date	08/10/2020
	Survey held at	8 Kaki Bukit Avenue 4 Premier #01-49		
	Repairer	1ST AUTO PRO PTE LTD		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	