LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Attn:

Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Azlan, Syazairdina Date: 09 Oct 2020

Preliminary Advice

Vehicle No : SLH5065X Accident Date : 07/10/2020 : MITSUBISHI OUTLANDER Make Policy No. : 2100489461 **Assignment Date** : 08/10/2020 **Excess** : S\$600.00

Date of Inspection : 08/10/2020 Est. Duration of Repair : 6 Inspection At : CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (PANDAN GARDENS)

209 PANDAN GARDENS SINGAPORE 609339

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 9,648.70 |
|-----------------------------|------|----------|
| Revised Amount | :S\$ | 5,384.45 |
| Check Items (Estimated) | :S\$ | 1,805.38 |
| Total | :S\$ | 7,189.83 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 78,000.00 COE / PARF Rebate 53,183.00 :S\$

Salvage Value :S\$

Margin for Repair 24,817.00 :S\$

Remarks

| X | () | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. |
|---|-----|---|
| |) | The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. |
| |) | Other comments : |