LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur Date: 08 Oct 2020

Preliminary Advice

Vehicle No: SMD1960YAccident Date: 05/10/2020Make: MITSUBISHI OUTLANDERPolicy No.: 1800091113Assignment Date: 06/10/2020Excess: \$\$600.00

Date of Inspection : 07/10/2020 Est. Duration of Repair : 6
Inspection At : CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (PANDAN GARDENS)

209 PANDAN GARDENS SINGAPORE 609339

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 7,382.10 |
|-----------------------------|------|----------|
| Revised Amount | :S\$ | 5,305.32 |
| Check Items (Estimated) | :S\$ | 1,218.97 |
| Total | :S\$ | 6,524.29 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

 Pre-Accident Value
 :S\$
 88,000.00

 COE / PARF Rebate
 :S\$
 44,311.00

Salvage Value :S\$

Margin for Repair :S\$ 43,689.00

Remarks

| Х |) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. |
|---|---|---|
| |) | The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. |
| |) | Other comments : |