

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd
20 McCallum Street
#09-01 Tokio Marine Centre
Singapore 069046

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ng Kwai Kay Francis

Date: 13 Oct 2020

Preliminary Advice

Insured Vehicle No	: GBG3478A		
TP Vehicle No	: SHB2533K	Accident Date	: 08/10/2020
Make	: HYUNDAI IONIQ HYBRID	Assignment Date	: 08/10/2020
Date of Inspection	: 08/10/2020	Est. Duration of Repair	: 3 days
Inspection At	: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,827.52
Revised Amount	:S\$	3,468.72
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,468.72

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP