

BM WHEELPOWER PTE. LTD.

R REF.: SKP8868X

REF.: SJA189R

AIG INSURANCE

MOTOR CLAIMS DEPARTMENT

*Not Authorized
L1 Pump @ 7450/hr
Pursuing After Pains
Folks*



bm wheelpower

DATE: 9/10/2020
FROM: Lee Shirley
FAX: 6452 5333
CONTACT: 8686 5188
MAKE & MODEL: AUDI TTC 2.0 TFSI S-TRONIC
CHASSIS NO.: TRUZZZ8J871038195
ENGINE NO.: BWA145538
YEAR MADE: 2007
ACCIDENT DATE: 8 October 2020

IMATE FOR VEHICLE NO.: SJA189R

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	DOOR GLASS RH		1	\$ <i>SL</i> X 360.00
2	DOOR GLASS MOULDING RH		1	\$ <i>SL</i> X 80.00
3	DOOR RH <i>2450</i>		1	\$ <i>SL</i> ✓ 2,700.00
4	DOOR SEAL RH		1	\$ <i>SL</i> 300.00 X
5	DOOR RH HINGE UPPER		1	\$ <i>R</i> X 70.00
6	DOOR RH HINGE LOWER		1	\$ <i>R</i> X 200.00
7	REAR FENDER RH		1	\$ <i>SL</i> ✓ 760.00
8	REAR FENDER INNER SHIELD RH		1	\$ <i>SL</i> X 160.00
9	REAR FENDER INNER SHIELD CLIP		10	\$ <i>SL</i> X 80.00
10	SIDE PANEL RH		1	\$ <i>R</i> X 2,000.00
11	ROCKER PANEL GARNISH RH		1	\$ <i>SL</i> ✓ 600.00
12	REAR RH TIE ROD		1	\$ <i>SL</i> 200.00 X
13	REAR KNUCKLE ARM RH <i>495</i>		1	\$ <i>SL</i> 850.00 ✓
14	REAR KNUCKLE ARM BEARING RH		1	\$ <i>SL</i> 300.00 ✓
15	REAR RH CONNECTING LINK		1	\$ <i>SL</i> X 100.00
16	STABILIZER LINK RH		1	\$ <i>SL</i> 250.00 X
17	REAR RH SHOCK ABSORBER		1	\$ <i>SL</i> 300.00 X
18	REAR BUMPER		1	\$ <i>SL</i> 1,500.00
19	REAR BUMPER RETAINER RH		1	\$ <i>SL</i> 75.00
20	REAR BUMPER SPONGE		1	\$ <i>SL</i> X 100.00
21	REAR BUMPER SENSOR		4	\$ <i>SL</i> X 1,000.00
22	REAR BUMPER CLIP		10	\$ <i>SL</i> ✓ 80.00
TOTAL:				\$ 12,065.00
LESS 5%:				\$ (603.25)
PARTS TOTAL:				\$ 11,461.75

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

BM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
T 6262 8888 F 6452 5333
COMPANY REG. NO.: 200204110W

SPECIAL NETT

WINDSCREEN SEALANT	1	\$	405m	50.00
BODY SEALANT	1	\$	30L	50.00
TYRE SPORT RIM 1004-80	1	\$	1004 ✓	1,800.00
CONTINENTAL SPORTCONTACT 6 TYRE (RH REAR)	1	\$	PN X	500.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS	\$	900	1,600.00
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	\$	100	150.00
TO REMOVE & REPLACE RH DOOR GLASS	\$	60	100.00
TO REMOVE, RENEW & REFIT REAR RH TYRE	\$	20	150.00
TO REMOVE AND REPLACE FUEL TANK FIXTURE AND TO UPHOLSTERY TO FACILITATE REPAIRS	\$	✓	50.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	30	150.00
TO REMOVE & REFIT ALL SENSOR	\$	50	100.00
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$	PN X	200.00
TO REMOVE & REFIT REAR RH UNDERCARRIAGE	\$	80	150.00
TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	\$	60	120.00
TO APPLY ANTI RUST COATING	\$	60	80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	900	1,600.00

TOTAL:	\$	18,311.75
7% GST:	\$	1,281.82
GRAND TOTAL:	\$	19,593.57