

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Tuesday, 13 October 2020 4:03 pm
To: Kelvin Chew
Cc: suhaimi@alpinemotors.sg; vincent.sim@alpinemotors.sg; SUR
Subject: RE: SLB 1845U OD (AIG) DOA - 07/10/2020

Dear Kelvin,

As spoken, according to our surveyor, repair limit should be \$ 10,500.00, please check & revert whether you are able to undertake within the repair limit.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

From: Kelvin Chew <kelvin.chew@firstautoworks.com.sg>
Sent: Monday, 12 October 2020 4:54 pm
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: suhaimi@alpinemotors.sg; vincent.sim@alpinemotors.sg; SUR <sur@lkkauto.com>
Subject: Re: SLB 1845U OD (AIG) DOA - 07/10/2020

Dear Shirley,

Workshop request lumpsum repair limit \$16k.

Kindly please advice on excess amount.

thanks.

from,

kelvin

On 2020-10-12 11:05, Shirley Hiew (LKK Auto) wrote:

Dear Kelvin,

According to our surveyor, repair limit is \$ 16,000.00, please check & revert whether you are able to undertake within the repair limit.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.