

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

09-10-20

OUR REF NO. SJN 8545A

LEONG KWAN CHIANG
BLK 159 LORONG 1 TOA PAYOH,
#02-1528
SINGAPORE 310159

Steve (LKK) 8322 8813
WHL M/L
9/10/20, 3-30pm
L/S, 4 dy,
By AL SH

ESTIMATE BILL FOR VEHICLE NO. SJN 8545A MODEL : TOYOTA ALTIS 1.6A

<u>LIST ITEM</u>			
1) FRONT BUMPER	X R		\$ 544.21
2) FRONT BUMPER CLIPS	X NM	10PCS @\$8.90	\$ 89.00
3) FRONT BUMPER SIDE ATTACHEMENT (RH)	X NM		\$ 48.65
4) FRONT FENDER (RH)	/ DD		\$ 484.00 /
5) FRONT FENDER EMBLEM (RH) "VVT-i"	/ MC		\$ 67.75 /
6) FRONT FENDER INNER SHIELD (RH)	X NM		\$ 231.00
7) FRONT FENDER INNER SHIELD CLIPS (RH)	X NM	10PCS @\$8.90	\$ 89.00
8) FRONT SPORT RIM (RH)	/ CM		\$ 478.00 350 /
9) FRONT SHOCK ABSORBER (RH)	X NM		\$ 453.20
10) FRONT KNUCKLE ARM (RH)	X NM		\$ 438.00
11) FRONT KNUCKLE ARM BEARING (RH)	X NM		\$ 231.00
12) FRONT LOWER ARM (RH)	X NM		\$ 328.00
13) FRONT LOWER ARM BALL JOINT (RH)	X NM		\$ 128.19
14) FRONT WHEEL BEARING HUB (RH)	X NM		\$ 283.00
15) WING MIRROR (RH)	X R		\$ 538.00
16) WING MIRROR COVER (RH)	X NM		\$ 138.90
17) FRONT DOOR (RH)	/ DD		\$ 863.00 /
18) FRONT DOOR STICKER (RH)	/ MC		\$ 93.70 /
19) FRONT DOOR PROTECTOR (RH)	/ CM		\$ 183.00 /
20) FRONT DOOR GLASS OUTER CHROME MOULDING (RH)	X NM		\$ 163.00

21) FRONT DOOR HINGE (RH) / OT	2PCS @\$81.26	\$ 162.52 /
22) FRONT DOOR CHECKER (RH) X NM		\$ 187.40
23) FRONT DOOR WEATHERSTRIPE (RH) X NM		\$ 144.20
24) FRONT DOOR INNER TRIM BOARD (RH) X NM		\$ 780.10
25) FRONT DOOR GLASS CHANNEL (RH) X NM		\$ 84.70
26) FRONT DOOR GLASS REGULATOR (RH) ? / OT		\$ 171.20 /
27) FRONT DOOR GLASS REGULATOR MOTOR (RH) X NM		\$ 236.20
28) FRONT DOOR LOCK (RH) ? / Jammed		\$ 259.20 /
29) FRONT DOOR STRIKER (RH) X NM		\$ 48.40
30) REAR DOOR (RH) X R		\$ 793.37
31) REAR DOOR PROTECTOR (RH) X NM		\$ 144.80
32) REAR DOOR STICKER (RH) X NM		\$ 141.60
33) ROCKER GARNISH (RH) X R		\$ 573.00
34) ROCKER GARNISH CLIPS (RH) X NM	8PCS @\$8.90	\$ 71.20

2634-37
-25%
1975-77

\$ 9,670.49
\$ 2,417.62
\$ 7,252.87

LESS DISCOUNT - 25%

P- 1975-77
L- 1629
3595-77

\$ 250.00
\$ 250.00

SPECIAL NETT ITEM

1) FRONT TYRE (RH) X NM

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM

L/S- 2876-61

\$ 80.00 JO

2) TO APPLY UNDER SEALING ON AFFECTED AREAS = 2900

\$ 120.00 JO

3) TO REMOVE AND REFIX FRONT UNDERCARRIAGE ASSY (RH)

\$ 32.00 X

4) TO CONDUCT 4 WHEEL ALIGNMENT

\$ 120.00 60

5) TO REMOVE AND REFIX FRONT & REAR FOOR (RH) FIXING AND REALIGNMENT

\$ 440.00 X

6) TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC

1629

\$ 1,100.00 500

\$ 1,100.00 1000

\$ 2,992.00

GRAND TOTAL : \$ 10,494.87

7) TO RESPRAY ON AFFECTED AREAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: