



Exceptional Journeys

Surveyor : RASUL
Claim : AIG OD
DOA : 10.10.2020
Emailed : 10.11.2020, 2.40pm
Date Survey : 12.10.2020

VEHICLE NO : SMA 7829 X
MODEL : MIT OUTLANDER 2.0
WIP : 58355

Table with 2 columns: Description and Amount. Rows include Material (\$10,599.05), Labour (\$5,210.00), Sub-Total (\$15,809.05), Less Excess (\$300.00), Total (\$15,509.05), GST 7% (\$1,085.63), Grand Total (\$16,594.68), and Finalise By/Date (LOI / 10/11/2020).

[X] REVERT BACK WITHIN 7 DAYS, OTHERWISE WILL PROCEED WITH INVOICING

[ ] SURVEYOR'S REPORT REQUIRED

[ ] REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends + 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

[ ] TP claim

[ ] Claim GIA / LTA fee

[ ] Claim Loss of [ ] Use / [ ] Rental

[ ] Claim Medical Fee / Others

[ ] Third Party Report -



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892  14/10/2020	Cust No/Name	KCV08661/Mr Tan Su Wai
	Reg No/Reg Date	SMA7829X / 20/06/2018
	Date In/Mileage	14/10/2020/ 74387
	Chassis/Package	GF7W0401722 /DC17S3C
	Engine No	4J11YC2390
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE (991)
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	09/11/2020/ 15:32	BLE	260 / AiTing	58355			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1800.00
REPLACE DAMAGED PARTS, REPLACE FRONT SUPPORT PANEL, BONNET, FRONT BUMPER, RH FRONT FENDER, LH FRONT FENDER, REPAIR RH FRONT DOOR, LH FRONT DOOR, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓
E PNT88000								100.00
REMOVE AND INSTALL RADIATOR AND A/COND CONDENSER TO FACILITATE REPAIR								?
A 55900099								80.00
TOP UP A/COND GAS AND CHECK A/COND SYSTEM								?
E PNT98000								2450.00
RESPRAY ON FRONT SUPPORT PANEL, BONNET, FRONT BUMPER, RH FRONT FENDER, LH FRONT FENDER, LH FRONT DOOR, RH FRONT DOOR, AND ALL OTHER AFFECTED PORTIONS TO THE SAME								✓
M SUNDRY								40.00
APPLY BODY SEALANT ON AFFECTED AREAS								✓
A 54900099								30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								✓
M SUNDRY								40.00
PERFORM RUST PREVENTION ON AFFECTED AREAS								✓
A 10028901								120.00
CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓
M SUNDRY								480.00
REAPPLY ZERTONA PAINT PROTECTION ON AFFECTED AREAS								?
M SUNDRY								20.00
SUNDRIES								✓
S SPECIALISTJOB								50.00
SUPPLY & REPLACE FRONT LICENSE PLATE WITH FRAME								✓
X EXC								-300.00
EXCESS								
X PNL,HEADLAMP SUPT,UPR RH					1.00	?	58.00 23.00	44.66
X PANEL,HEADLAMP SUPPORT,UPR					1.00	?	182.00 23.00	140.14
X PNL,HEADLAMP SUPT,UPR LH					1.00	?	58.00 23.00	44.66
X RADIATOR ASSY					1.00	?	1091.00 23.00	840.07

This is not an official tax invoice.  
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

Co Reg No : 197701469G


THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for AIG Asia Pacific Insurance Pte. Ltd. and vehicle information for a Mitsubishi Outlander.

Main invoice table with columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No, Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts and their costs.

This is not an official tax invoice. This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**  
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892  14/10/2020	Cust No/Name	KCV08661/Mr Tan Su Wai
	Reg No/Reg Date	SMA7829X / 20/06/2018
	Date In/Mileage	14/10/2020/ 74387
	Chassis/Package	GF7W0401722 /DC17S3C
	Engine No	4J11YC2390
	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE (991)
	Colour/Trim	X04 BLACK / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	09/11/2020/ 15:32	BLE	260 / AiTing	58355

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X PIPE,A/C CONDENSER OUTLET <i>→ Supp</i> Z TEXT AIG OD CLAIM DOA : 10.10.20 SURVEYOR RASUL LKK 12.10.20 POLICY NO : 1800069446-01	1.00	262.00	23.00	201.74
Pro Forma				
<i>Guarantee Your Warranty, Maintain with Cycle &amp; Carriage!</i>				

Parts	10,599.05		Nett	15,509.05
Labour	4,580.00	7% GST on	15509.05	1085.63
Standard Menu	0.00			
Specialist Job	50.00		Total Payable	16,594.68
Diagnostics Job	0.00			
Sundry/Others	280.00			
Total(w/o GST)	15,509.05			

This is not an official tax invoice.  
 This is a computer generated document, no signature is required.



## Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SMA 7829 X

<u>Materials</u>		<u>Cost (\$)</u>
1	Panel, headlamp support, RH	58.00
2	Panel, headlamp support, LH	58.00
3	Grille assy, radiator	569.00
4	Cover, headlamp supt panel	50.00
5	Horn, Theft protection	92.00
6	Tape, Tailgate (x4)	16.00
7	Plug, Body	6.00
8	Clip (x10)	20.00
9	Clip (x10)	30.00
10	Pipe, A/C condenser outlet	262.00
		-----
Total		1,161.00
Less 23% discount		267.03
Total after discount		893.97
7% GST		62.58
		-----
<b>Grand total</b>		<b><u>\$ 956.55</u></b>

Thank You.

Yours faithfully

LOI AI TING  
SENIOR OFFICER - ADMIN  
**MITSUBISHI SERVICE CENTRE**  
DID : 6568 4556 / 6568 4501  
FAX : 6567 5258 / 6565 1240





DATA 482900

After repair to verify PROBLEMS UNIT HAS BEEN ALL THE GOOD

2020.10.23

Signature: [Handwritten Signature] / u d AC

All DTCs

Item	Setting	Information
M.U.T.-3 Version		SEW20011-00
V.C.I. Version		B177
Vehicle Information		DBA-GF7W 2017MY

All DTCs

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCs	
Auto Stop & Go (AS&G)	ASG_25080000		No DTCs	
AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45880040		No DTCs	
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs	
SRS-AIR BAG	ORC_81047302		No DTCs	
Air Conditioner	AC_80080011		No DTCs	
ETACS	ETACS_83040801		No DTCs	
Meter	MTR_84084001		No DTCs	
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
AND	AND_8C080002		Non-equipped System or Communication Error	
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error	
LIN	ETACS_83040801		Non-target System	
Power Gate	ETG_92080000		Non-equipped System or Communication Error	

All DTCs

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/Keyless	KOS_8A880020		No DTCs	
OSS	OSS_9588000B		No DTCs	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/DW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	