



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED  
 36 ROBINSON ROAD  
 #16-01 CITY HOUSE  
 SINGAPORE 068877

Registration No : SKN8797C  
 Chassis No : JHMRU1810JX202548  
 Model : HRV DX-SIN CVT YM 2018  
 Owner's Name : XING ZHONG CONSTRUCTION PTE. LTD.  
 Ins Policy No. : 20-MR001890-R00  
 Date of Accident : 7/10/2020

Document No. : SQT20003262  
 Date : 8. Oct 2020  
 Customer No. : WZF002  
 Svc Advisor : ARY CHUA WAI NGEE  
 Engine No : L15B5672556  
 Date | Time : 8. Oct 2020 4:44:52 PM  
 Surveyor Name : CID : 65 5846 5873

Page 1

Survey Date : 08/10/2020  
 Authorisation Date : 08/10/2020  
 Email : arychua@honda.com.sg

| Item            | Description                                                                                                                                                                                                                                                                                         | Qty | Unit Price | Disc %      | Amount  | 0% GST Amount | Amount Incl GST |
|-----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------------|-------------|---------|---------------|-----------------|
|                 | TP DIRECT SETTLEMENT (J/NO: 752)<br>OWNER: XING ZHONG CONSTRUCTION PTE. LTD<br>OWNER INSURER: TOKIO MARINE INSURANCE LTD<br>ACC DATE: 07/10/2020@17.00PM<br>ACC: BLK 826 YISHUN ST 81 OPEN CARPARK<br>TP VEHICLE: SHD3549Z - HYUNDAI/40/BLUE TAXI<br>TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED |     |            |             |         |               |                 |
| 33150-T7A-E51   | HEADLIGHT ASSY,L. <i>ny</i>                                                                                                                                                                                                                                                                         | 1   | 1335.40    | <i>X</i>    | 1001.55 | 70.11         | 1071.66         |
| 04711-T7A-J00ZZ | FACE,FR.BUMPER <i>De/neged</i>                                                                                                                                                                                                                                                                      | 1   | 487.90     | <i>/</i>    | 365.92  | 25.61         | 391.53          |
| 71106-T7A-J10   | GARNISH,L.FR.FOG LIGHT <i>ny</i>                                                                                                                                                                                                                                                                    | 1   | 24.90      | <i>X</i>    | 18.67   | 1.31          | 19.98           |
| 71130-T7A-J00ZZ | BEAM COMP,FR.BUMPER <i>ny</i>                                                                                                                                                                                                                                                                       | 1   | 249.50     | <i>X</i>    | 187.12  | 13.10         | 200.22          |
| 91505-TM8-003   | CLIP,BUMPER <i>ny</i>                                                                                                                                                                                                                                                                               | 10  | 2.30       | <i>/</i>    | 17.25   | 1.21          | 18.46           |
| 74157-T7B-003   | PROTECTOR,L.FR.WHEEL ARCH <i>ny</i>                                                                                                                                                                                                                                                                 | 1   | 157.60     | <i>/</i>    | 118.20  | 8.27          | 126.47          |
| 71190-T7A-J00   | BEAM,L.FR.BUMPER UPPER                                                                                                                                                                                                                                                                              | 1   | 32.50      | <i>?</i>    | 24.37   | 1.71          | 26.08           |
| 71198-T7A-J00   | SPACER,L.FR.BUMPER SIDE <i>ny</i>                                                                                                                                                                                                                                                                   | 1   | 11.30      | <i>/</i>    | 8.47    | 0.59          | 9.06            |
| 71193-T7A-J00   | SPACER,R.FR.BUMPER SIDE <i>ny</i>                                                                                                                                                                                                                                                                   | 1   | 11.30      | <i>X</i>    | 8.47    | 0.59          | 9.06            |
| Sum Item        |                                                                                                                                                                                                                                                                                                     |     |            |             | 1750.02 | 122.50        | 1,872.52        |
| BOSUN           | SUNDRIES <i>ny</i>                                                                                                                                                                                                                                                                                  | 1   | 40.00      | <i>20</i>   | 40.00   | 2.80          | 42.80           |
| BML01I          | INSPECT FR LIGHTING MECHANISMS & FOCUS                                                                                                                                                                                                                                                              | 1   | 160.00     | <i>80</i>   | 160.00  | 11.20         | 171.20          |
| BKBH01S         | STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS. <i>650</i>                                                                                                                                                                                                                                           | 1   | 1400.00    | <i>650</i>  | 1400.00 | 98.00         | 1498.00         |
| BP03R           | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P) <i>520</i>                                                                                                                                                                                                                                       | 1   | 1800.00    | <i>1040</i> | 1800.00 | 126.00        | 1926.00         |
| Sum Labor       |                                                                                                                                                                                                                                                                                                     |     |            |             | 3400.00 | 238.00        | 3,638.00        |

Survey By

Date & Time

Excess

Total Amount 5,150.02 360.50 5,510.52

Total (Inclusive of GST) 5,510.52

Printed on 8/10/2020 8:07:06 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.