



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC20011005/Ktd3n2	Date: 05/08/2021
			Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBK 2375Z	Veh. Inspected	GBG 4204S	
Policy No.		Coverage (\$)	0.00	
Claim No.	20/20/20/VC00/023754	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	12/10/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	FIAT FIORINO (A)	c.c	1248	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZFA22500006F47061	Colour	METALLIC GREEN	
Odometer	143803 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	YOKOHAMA	7 mm	
L/H Front Tyre	185/65 R15	YOKOHAMA	7 mm	
R/H Rear Tyre	185/65 R15	YOKOHAMA	7 mm	
L/H Rear Tyre	185/65 R15	YOKOHAMA	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	08/10/2020	Inspection Date	12/10/2020	
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			24 Working Days	