



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0754/2020/NS
DATE	:	9-Oct-20
WIP	:	52516

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR NG ZI HAO
ADDRESS	:	BLK 774 BEDOK RESERVOIR VIEW #04-105 SINGAPORE 470774
TELEPHONE	:	HP +65 91559340
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1700079236-02
VEHICLE NO	:	SLU 5949 C
MODEL CODE	:	AUDI SEDAN 1.4 TFSI S
MODEL YEAR	:	7/12/2017
ENGINE NO	:	CVN 047470
CHASSIS NO	:	WAUZZZF45JA036156
MILEAGE	:	38136KM
DATE IN	:	9-Oct-20
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	8-Oct-20
PLACE OF ACCIDENT	:	TAMAN SIREH



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 5949 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 250	
3	TO DISMANTLE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY.	S/N \$ 350.00 280	
4	TO DISMANTLE AND RENEW RONT BUMPER, RHS FRONT FENDER, BONET AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓	\$ 2,000.00 1500	
5	✓ TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR AND RHS WING MIRROR COVER. ✓	2350. 2,950.00	AXSSO = 2200 Mirror = 150
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>6,402.00</u>	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5949 C

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/	NETT	
1	FRONT BUMPER <i>Rebuilt</i>	\$	2,111.00	✓	
2	FRONT BUMPER FIXING PARTS <i>None</i>	\$	282.00	+	
3	FRONT BUMPER SECURING STRIP <i>?</i>	2	70.00	?	
4	FRONT BUMPER GRILLE - CENTRE <i>None</i>	\$	194.00	+	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>None</i>	\$	208.00	+	
6	FRONT BUMPER AIR GUIDE - RH <i>missing?</i>	\$	62.00	✓	?
7	RADIATOR GRILLE <i>None</i>	\$	1,139.00	+	
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>cut</i>	\$	134.00	✓	
9	FRONT BUMPER CARRIER <i>Not Nec</i>	\$	795.00	+	
10	FRONT BUMPER GUIDE SECTION - RH <i>Damaged</i>	\$	37.00	-	
11	FRONT BUMPER COVER <i>None</i>	\$	126.00	+	
12	FRONT BUMPER FOAM FILLER PIECE <i>None</i>	\$	123.00	+	
13	CAUTION SIGN STICKER <i>None</i>	NEC	14.00	+	
14	AIRCON STICKER	NEC	8.00	+	
15	LOCK CARRIER BRACKET <i>None</i>	\$	136.00	+	
16	LOCK CARRIER BRACKET SUPPORT - LH / RH <i>None</i>	\$	56.00	+	
17	HORN - RH LOW TONE <i>None</i>	\$	124.00	+	
18	SPRING SHACKLE - RH <i>None</i>	\$	29.00	+	
19	FRONT FENDER - RH <i>Distorted</i>	\$	758.00	✓	
20	FRONT FENDER ATTACHMENT PARTS <i>None</i>	\$	200.00	+	
SUB TOTAL SPARE PARTS			:	\$	6,606.00



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5949 C

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/	NETT	
21	FRONT FENDER CLOSING ELEMENT - RH ?	\$		49.00	?
22	FRONT FENDER BRACKET - RH Bent	\$		35.00	✓
23	DEFORMATION ELEMENT BRACKET - RH ?	\$		49.00	?
24	FRONT FENDER INNER REAR BRACKET ?	\$		31.00	?
25	FRONT FENDER BRACE - RH Bent	\$		117.00	✓
26	WHEEL HOUSING LINER - RH Del'd	\$		239.00	✓
27	WHEEL HOUSING LINER ATTACHMENT PARTS 14 ?	\$		90.00	?
28	WHEEL SPOILER Torn	\$		73.00	✓
29	WHEEL SPOILER TRIM - RH ?	\$		36.00	?
30	SOME CHIP GUARD - RH New	\$		50.00	✓
31	TOP FENDER LEDGE COVER - INNER ?	\$		31.00	?
32	TOP FENDER LEDGE COVER - OUTER Del'd	\$		23.00	✓
33	BONNET Pented	\$		2,763.00	+
34	BONNET ATTACHMENT PARTS New	\$		121.00	✓
35	BONNET IMPACT PROTECTION - CENTRE 2 New	\$		27.00	✓
36	BONNET IMPACT PROTECTION - RH	\$		27.00	✓
37	BONNET IMPACT PROTECTION - LH	\$		28.00	✓
38	LED HEADLIGHT - RH Cashed	\$		7,693.00	✓
39	MAIN LIGHT ELECTRONICS POWER MODULE 2 Not	\$		739.00	+
40	LIGHT CONTROL SYSTEM CONTROL UNIT 1 New	\$		742.00	+
SUB TOTAL SPARE PARTS			:	\$	12,963.00



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5949 C

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/	NETT	
41 LIFT CYLINDER - RH	?	\$	208.00	?
42 EXTERIOR MIRROR MOUNTING - RH	lit	\$	886.00	✓
43 MIRROR CAP - RH	Repair	\$	261.00	X.
44 WINDOW SLOT SEAL - RH	lit	\$	303.00	+
45 FRONT ALUMINIUM RIM - RH	lit	\$	684.00	✓
46 FRONT NO PLATE	lit	\$	60.00	+
47 SUNDRIES	?	\$	300.00	?
TOTAL SPARE PARTS	:	\$	22,271.00	
TOTAL LABOUR CHARGES	:	\$	6,402.00	
GRAND TOTAL	:	\$	28,673.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian King
: 12/10/20
:
:
:
: Not Authorised, 06 Days.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- **Parts prices** are subject to confirmation
- **Third party survey** is on a "Without Prejudice" basis
- No **illegal modification(s)** is allowed
- **Supplementary item(s)** must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT