

Cov-in 15/10/2020.

WIP 52516

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Kiam/Hong 

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5949 C

AIG - Adrian

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Rehnd</i>		\$	2,111.00	✓
2	FRONT BUMPER FIXING PARTS <i>Not in</i>		\$	282.00	+
3	FRONT BUMPER SECURING STRIP	2	\$	70.00	+
4	FRONT BUMPER GRILLE - CENTRE <i>Not in</i>		\$	194.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Not in</i>		\$	208.00	+
6	FRONT BUMPER AIR GUIDE - RH <i>missing - Rehnd</i>		\$	62.00	✓ ✓
7	RADIATOR GRILLE <i>Not in</i>		\$	1,139.00	+
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Not in</i>		\$	134.00	✓
9	FRONT BUMPER CARRIER <i>Not in</i>		\$	795.00	+
10	FRONT BUMPER GUIDE SECTION - RH <i>Damaged</i>		\$	37.00	-
11	FRONT BUMPER COVER <i>Not in</i>		\$	126.00	+
12	FRONT BUMPER FOAM FILLER PIECE <i>Not in</i>		\$	123.00	+
13	CAUTION SIGN STICKER	NEC	\$	14.00	+
14	AIRCON STICKER	NEC	\$	8.00	+
15	LOCK CARRIER BRACKET <i>Not in</i>		\$	136.00	+
16	LOCK CARRIER BRACKET SUPPORT - LH / RH <i>Not in</i>		\$	56.00	+
17	HORN - RH LOW TONE <i>Not in</i>		\$	124.00	+
18	SPRING SHACKLE - RH <i>Not in</i>		\$	29.00	+
19	FRONT FENDER - RH <i>Distorted</i>		\$	758.00	✓
20	FRONT FENDER ATTACHMENT PARTS <i>Not in</i>		\$	200.00	+
SUB TOTAL SPARE PARTS			\$	6,606.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 5949 C

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
21	FRONT FENDER CLOSING ELEMENT - RH <i>Best</i>	1	\$ 49.00	✓
22	FRONT FENDER BRACKET - RH <i>Best</i>	1	\$ 35.00	✓
23	DEFORMATION ELEMENT BRACKET - RH	1	\$ 49.00	?
24	FRONT FENDER INNER REAR BRACKET	1	\$ 31.00	?
25	FRONT FENDER BRACE - RH <i>Best</i>	1	\$ 117.00	✓
26	WHEEL HOUSING LINER - RH <i>Del'd</i>	1	\$ 239.00	✓
27	WHEEL HOUSING LINER ATTACHMENT PARTS <i>NA</i>	1	\$ 90.00	?
28	WHEEL SPOILER <i>storn</i>	1	\$ 73.00	✓
29	WHEEL SPOILER TRIM - RH	1	\$ 36.00	?
30	STONE CHIP GUARD - RH <i>new</i>	1	\$ 50.00	✓
31	TOP FENDER LEDGE COVER - INNER <i>repl'd</i>	1	\$ 31.00	✓
32	TOP FENDER LEDGE COVER - OUTER <i>Del'd</i>	1	\$ 23.00	✓
33	BONNET <i>Painted</i>	1	\$ 2,763.00	✓
34	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 121.00	✓
35	BONNET IMPACT PROTECTION - CENTRE <i>?</i>	1	\$ 27.00	✓
36	BONNET IMPACT PROTECTION - RH <i>new</i>	1	\$ 27.00	✓
37	BONNET IMPACT PROTECTION - LH	1	\$ 28.00	✓
38	LED HEADLIGHT - RH <i>cracked</i>	1	\$ 7,693.00	✓
39	MAIN LIGHT ELECTRONICS POWER MODULE <i>2 not NA</i>	1	\$ 739.00	✗
40	LIGHT CONTROL SYSTEM CONTROL UNIT <i>1 not NA</i>	1	\$ 742.00	✗
SUB TOTAL SPARE PARTS			\$ 12,963.00	

Adrian Lj
 15/10/20
 H.S.