

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM20011055/Evd3e2 AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE Date: 20-10-2020 068811 ATTN: VALE OH Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SBJ 7E Veh. Inspected **GBD 1158C** Policy No. Coverage (\$) 0.00 S0M02VCC Excess (\$) 0.00 Claim No. **Assign From** VALE OH **Assign Date** 12/10/2020 2. **Vehicle Particulars & Condition** Make & Model **NISSAN CABSTAR** 2953 c.c **Engine No. HIDDEN** Year of Reg. 2014 JN1SC2F24Z0855868 Chassis No. Colour **SILVER** Odometer **IN ORDER** Steering **IN ORDER** STANDARD ALLOY RIM Brakes Modification FAIR General **Conditions of Tyres** 3. Size Make **Balance** 185 R15C YOKOHAMA 4 mm R/H Front Tyre 185 R15C YOKOHAMA L/H Front Tyre 4 mm R/H Rear Tyre 185 R15C YOKOHAMA 4 mm 185 R15C YOKOHAMA 4 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. 5. **General Information** Inspect Date / Time 13/10/2020 ( 11:05 AM ) **Accident Date** 8 KAKI BUKIT AVE 4 # 03-46 PREMIER Survey held at **GARAGE 13 PTE LTD** Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000

Report Ref No. CS3/ASM20011055/Evd3e2

**Estimate Days of Repair** 

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

5b.

CHEN TSUE YEE

K.K.LAU CPT(RET)

**Automotive Assessor** 

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

**6 Working Days** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.