



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 18/19/19/VP02/285935

Date: 02nd November 2020

Our Ref: CS1/LPM20011095/Gvf3s2

M/s Lonpac Insurance Bhd

21st Floor, Bangunan Public Bank
No. 6 Jalan Sultan Sulaiman
50000 Kuala Lumpur, Malaysia

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJR 5318M
INSURED VEHICLE: WRS 3488 ACCIDENT DATE: 01/06/2019**

We thank you for your instruction on 13/10/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJR 5318M from M/s Prestige Appraiser Services.
- b) Polis Diraja Malaysia of Vehicles SJR 5318M, BET 1354, WRS 3488 and JBTR: 013965/19.
- c) Colour damaged vehicle photographs of SJR 5318M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJR 5318M
Make & Model	: Toyota Camry
Year of Registration	: 2009
Chassis Number	: MR053BK4107046504
Engine Capacity	: 1998 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.