

REPAIR DETAILS

Repairer Estimates

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Oct 2020)
 Parts: 143 HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SH8824U/14/10/2020 09:25
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOT LID / DD	20.00	0.00	*2,174.90 FL ✓
2	2		*BOOT LID HINGE LH/RH X NM	20.00	0.00	*284.60 FL X
3	1		*BOOT LID LOCK UPPER X NM	20.00	0.00	*114.90 FL X
4	1		*BOOT LID LOCK LOWER / BT	20.00	0.00	*31.90 FL ✓
5	1		*BOOT LID I40 PLATE / MC	20.00	0.00	*27.90 FL ✓
6	1		*BOOT LID CRDI PLATE / MC	20.00	0.00	*27.90 FL ✓
7	1		*BOOT LID H EMBLEM PLATE / MC	20.00	0.00	*31.10 FL ✓
8	2		*BOOT LID LAMP LH/RH (LH) / LUT (RH) ? X NM	20.00	0.00	147.40 *287.80 FL ✓
9	1		*BOOT LID TRIMBOARD / CRU	20.00	0.00	*28.30 FL ✓
10	1		*BOOT LID LICENSE LAMP X NM	20.00	0.00	*1.70 FL X
11	10		*BOOT LID TRIM CLIP X NM	20.00	0.00	*2,279.00 FL X
12	1		*BOOT LID MOULDING / CR	20.00	0.00	*85.00 FL ✓
13	1		*BOOT LID LOWER GARNISH / CR	20.00	0.00	*227.90 FL ✓
14	1		*REAR BUMPER / OR	20.00	0.00	*1,106.00 FL ✓
15	1		*REAR BUMPER REINFORCEMENT / OR	20.00	0.00	*428.40 FL ✓
16	1		*REAR BUMPER SPONGE / OR	20.00	0.00	*119.50 FL ✓
17	2		*REAR BUMPER REINFORCEMENT BRACKET LH/RH X	20.00	0.00	*160.60 FL X
18	10		*REAR BUMPER CLIP / MC	20.00	0.00	*22.00 FL ✓
19	2		*REAR BUMPER SIDE BRACKET LH/RH / OR	20.00	0.00	*71.20 FL ✓
20	1		*REAR BUMPER UNDER COVER / CMT	20.00	0.00	*228.00 FL ✓
21	1		*REAR PANEL / DD	20.00	0.00	*526.70 FL ✓
22	1		*REAR PANEL GRANISH / CRU	20.00	0.00	*57.70 FL ✓
23	1		*REAR PANEL LOWER PANEL / DD	20.00	0.00	*495.50 FL ✓
24	1		*REAR PANEL TYRE HOLDER ? X NM	20.00	0.00	*248.00 FL X
25	1		*SPARE WHEEL LOCK NUT ? X NM	20.00	0.00	*17.80 FL X
26	1		*SPARE TYRE PANEL X R	20.00	0.00	*852.80 FL X
27	1		*SPARE TYRE PANEL CUSHION ? X NM	20.00	0.00	*223.10 FL X
28	1		*REAR FENDER LH / DD	20.00	0.00	*2,171.40 FL ✓
29	1		*REAR FENDER LH INNER TRIM X NM	20.00	0.00	*188.75 FL X
30	2		*TAIL LAMP LH/RH (LH) / CMT (RH) X NM	20.00	0.00	697.40 *1,395.60 FL ✓
31	1		*REAR BUMPER MAT / MC	0	0.00	*50.00 FS ✓
32	1		*REAR REVERSE SENSOR / SHAI	0	0.00	*135.70 FS ✓
33	1		*BOOT LIC COMFORT DELGRO STICKER / MC	0	0.00	*30.00 FS ✓
34	1		*BOOT LIC COMFORT TEL NO. STICKER / MC	0	0.00	*30.00 FS ✓
35	2		*REAR FENDER ADVERTISEMENT STICKER LH/RH (LH) / MC (RH) X NM	0	0.00	*200.00 FS 100 ✓
36	1		*REAR BOOTLID ADVERTISEMENT STICKER / MC	0	0.00	*100.00 FS ✓
37	1		*REAR BUMPER ADVERTISEMENT STICKER / MC	0	0.00	*50.00 FS ✓
38	1		*EXHAUST PIPE CENTRE X NM	20.00	0.00	*730.10 FL
39	1		*EXHAUST PIPE MUFFLER LH X NM	20.00	0.00	*967.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)

16,199.45

- List Item Discount on L Items (S\$)

3,120.75

Total Parts (S\$)

13,078.70

Estimates on Miscellaneous Items

Repairer Estimates

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	PK 11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New 1120	1,200.00
2	SPRAY PAINTING	New 800	900.00
3	REMOVE/REFIX UPHOLSTERY	New 30	120.00
4	REMOVE/REFIX EXHAUST PIPE	New X	90.00
5	TOWING FEE	New	60.00
6	REMOVE/REFIX REVERSE SENSOR	New 30	60.00
7	CHECK REAR LIGHTING	New 30	90.00
8	TUFF COATING	New 30	200.00
Gross Labour Cost (S\$)			2,720.00

ComfortDelGro Engineering Pte Ltd/SH8824U/14/10/2020 09:25. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ster (LKK)

WL PKL

P-6954.40

14/10/20, 10.00am

NI-495-70

L/S

MI-11

7 days

L-2100

9561-10

Ry AL SH

L/S - 7648.88
= 7650

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: