



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0773/2020/NS

19-Oct-20

Glory Tan

1 OF 1

SLQ 4048 E

AUDI A3 SEDAN 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
Parts			
1	Lock carrier <i>checked.</i>	\$ 719.00	✓ 575.00
2	Coolant <i>new</i>	\$ 91.00	✓ 72.32
Labours			
1	To remove and reinstall aircon condenser, additional radiator and radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas. <i>s/n</i>	1200	✓ ✓
2	To renew lock carrier and align to position.	\$ 2,100.00	1250 ✓
TOTAL		\$ 4,110.00	

For Premium Automobiles Pte Ltd

Adrian Ling.

19/10/20

8/8 Add 3 days.

Authorised Signature