

ASS. REC. BY:

REF:

MSG/ 20011116/Kqd3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

629257

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

835k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

24

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

/

EM not ready

27/08/21 @ 2.27pm Christina Wong informed TP convert OD, they have settled under TP subrogation claim from SOMPO.

29/12/21 Submit Preli. report.

Date/Time, File Pass to?

☐

: Preli. Report

1) 29/12 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

24

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

MER-TP

Lump Sum / I.B.I: (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 763761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST201001158E RCB NO:201001158E

M/S: SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555 FAX: 62213302
ATTN: Motor Claim Department

Claim No: ES2090802
Estimate No: ES2090802/YISHUN
Date: 09 Oct 2020
Policy No: D19MTPCVE003199
Veh Reg No: YN651B
Make/Model: ISUZU ISUZU
NPR75UH5A
Chassis No: JAANPR75H97101904
Engine No: 4HK1746253
Reg. Date: 10/10/2009

WS Ref: OD/SOMPO
Claim Type: Own Damage
Accident Date: 28/09/2020

Not Attached

11 Sep 8

Penny After Rain

24 days

Estimate Repair Cost to Vehicle No : YN651B

Description	U/Price	Quantity	Cost S\$	Amount S\$
Cost Plus				
1 FRONT WINDSCREEN GLASS	750.00	1 PC	750.00	✓
2 FRONT WINDSCREEN GLASS OUTER MOULDING	150.00	1 PC	150.00	✓
3 FRONT WINDSCREEN GLASS INNER SHIELD	50.00	1 PC	50.00	✓
4 FRONT WINDSCREEN GLASS LOWER MOULDING	80.00	1 PC	80.00	✓
5 TOP ROOF PANEL	710.00	1 PC	710.00	✓
6 TOP ROOF PANEL FRT INNER REINFORCEMENT	75.00	1 PC	75.00	✓
7 TOP ROOF PANEL SIDE INNER BEAMS	80.00	2 PCS	160.00	✓
8 CABIN REAR PANEL	826.00	1 PC	826.00	✓
9 CABIN REAR WINDSCREEN GLASS	145.00	1 PC	145.00	✓
10 CABIN REAR WINDSCREEN GLASS RUBBER	70.00	1 PC	70.00	✓
11 FRONT WINDSCREEN PILLAR OUTERS	980.00	2 PCS	1,960.00	✓
12 FRONT LH WINDSCREEN PILLAR INNER	120.00	1 PC	120.00	✓
13 TOP ROOF LINING	788.00	1 PC	788.00	✓
14 SUN VISOR	135.00	2 PCS	270.00	✓
15 FRONT INNER PANEL	539.00	1 PC	539.00	✓
16 FRONT WIPER PANEL	290.00	1 PC	290.00	✓
17 FRONT GRILLE	252.00	1 PC	252.00	✓
18 FRONT GRILLE CLIP	12.00	1 SET	12.00	✓
19 FRONT PANEL EMBLEM (ISUZU)	88.00	1 PC	88.00	✓
20 FRONT LH CORNAL GARNISH	118.00	1 PC	118.00	✓
21 DASHBOARD	480.00	1 PC	480.00	✓
22 DASHBOARD REINFORCEMENT	450.00	1 PC	450.00	✓
23 DASHBOARD LH GLOVE BOX	143.00	1 PC	143.00	✓
24 DASHBOARD LH GLOVE BOX COVER	58.00	1 PC	58.00	✓
25 DASHBOARD CENTRE LOWER	123.00	1 PC	123.00	✓
26 DASHBOARD CENTRE TOP GARNISH	199.00	1 PC	199.00	✓
27 FRONT LH SIDE MIRROR STAY	189.00	1 PC	189.00	✓
28 LH SIDE MIRROR SQUARE	80.00	1 PC	80.00	✓
29 LH SIDE MIRROR ROUND	32.00	1 PC	32.00	✓
30 FRONT LH SEAT	900.00	1 PC	900.00	✓
31 FRONT LH SAFETY BELT	235.00	1 PC	235.00	✓
32 FRONT LH STEP TRAY	74.00	1 PC	74.00	✓
33 AIR-CON BLOWER	350.00	1 PC	350.00	✓
34 AIRCON EVAPORATOR	1,150.00	1 PC	1,150.00	✓
35 AIRCON EVAPORATOR BRACKETS	42.00	2 PCS	84.00	✓
36 AIR-CON CONDENSER	285.00	1 PC	285.00	✓
37 HEADLAMP LH	228.00	1 PC	228.00	✓
38 LH SIGNAL LAMP	70.00	1 PC	70.00	✓
39 FRONT INNER AIRCON DUCTING	108.00	1 PC	108.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST201001158E RCB NO:201001158E

M/S: SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
 TEL: 64616555 FAX: 62213302
 ATTN: Motor Claim Department

WS Ref: OD/SOMPO
 Claim Type: Own Damage
 Accident Date: 28/09/2020

Claim No: ES2090802
 Estimate No: ES2090802/YISHUN
 Date: 09 Oct 2020
 Policy No: D19MTPCVE003199
 Veh Reg No: YN651B
 Make/Model: ISUZU ISUZU
 NPR75UH5A
 Chassis No: JAANPR75H97101904
 Engine No: 4HK1746253
 Reg. Date: 10/10/2009

Estimate Repair Cost to Vehicle No : YN651B

Description	U/Price	Quantity	Cost	Amount
			SS	SS
40 FRONT INNER SIDE AIRCON DUCTING	45.00	2PCS	90.00	?
41 SPEED METER	680.00	1PC	680.00	?
42 METER OUTER GARNISH	210.00	1PC	210.00	?
43 FUSES BOX ASSY	490.00	1PC	490.00	?
44 FUSES BOX OUTER COVER	29.00	1PC	29.00	?
45 ECU	650.00	1PC	650.00	?
46 FRONT WASHER TANK	85.00	1PC	85.00	?
47 HEATER DELAY	195.00	1PC	195.00	?
48 SIGNAL DELAY	48.00	1PC	48.00	?
49 FRONT WINDSCREEN PILLAR TOP GARNISHS	63.00	2PCS	126.00	?
50 STEERING WHEEL	310.00	1PC	310.00	?
51 STEERING SHAFT	490.00	1PC	490.00	?
52 FRONT DOORS	528.00	2PCS	1,056.00	?
53 FRONT LH DOOR GLASS	204.00	1PC	204.00	?
54 FRONT LH DOOR REGULATOR	104.00	1PC	104.00	?
55 FRONT LH DOOR REGULATOR MOTOR	140.00	1PC	140.00	?
56 FRONT LH DOOR CHANNEL	47.00	1PC	47.00	?
57 FRONT LH DOOR HINGE	65.00	2PCS	130.00	?
58 FRONT LH DOOR RUBBER	45.00	1PC	45.00	?
59 FRONT LH DOOR INNER LOCK	99.00	1PC	99.00	?
60 FRONT LH DOOR LOWER RUBBER	68.00	1PC	68.00	?
61 CABIN REAR LH MOUNTING	198.00	1PC	198.00	?
				18,185.00

Special Net

62 FRONT WINDSCREEN GLASS GUM	40.00	1PC	40.00	?
63 ERP BRACKET	18.00	1PC	18.00	?
64 TRUCK FRONT GATE	580.00	1PC	580.00	?
65 TRUCK FRONT WOODEN RAILING	400.00	1PC	400.00	?
				1,038.00

Labour

66 TOWING	80.00	1LA	80.00	?
67 REMOVE AND REFIX FRONT WINDSCREEN GLASS	100.00	1LA	100.00	?
68 REMOVE AND REFIX REAR WINDSCREEN GLASS	50.00	1LA	50.00	?
69 REMOVE & REFIX FRT BOTH DOOR'S GLASS (\$50X2)	100.00	1LA	100.00	?
70 REMOVE & REFIX SEAT, CARPET, GARNISH, TOP ROOF LINING, ETC	120.00	1LA	120.00	?

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
 TEL: 64616555 FAX: 62213302
 ATTN: Motor Claim Department

Claim No: ES2090802
 Estimate No: ES2090802/YISHUN
 Date: 09 Oct 2020
 Policy No: D19MTPCVE003199
 Veh Reg No: YN651B
 Make/Model: ISUZU ISUZU
 NPR75UH5A
 Chassis No: JAANPR75H97101904
 Engine No: 4HK1746253
 Reg. Date: 10/10/2009

WS Ref: OD/SOMPO
 Claim Type: Own Damage
 Accident Date: 28/09/2020

Estimate Repair Cost to Vehicle No : YN651B

Description	U/Price	Quantity	Cost	Amount
			SS	SS
71 REMOVE & REFIX STEERING WHEEL, SHAFT, CLUTCH, BRAKE PEDAL, FUEL PIPE ASSY, GEAR HANDLE ASSY & REALIGN STEERING WHEEL	150.00	1 LA	150.00	✓
72 REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
73 REMOVE & REFIX DASHBOARD, METER ASSY & CHECK WIRING	250.00	1 LA	250.00	✓
74 REMOVE & REFIX FRT GRILLE ASSY, HEADLAMPS, FRT PANEL, SIDE MIRROR ASSY, FRT WIPER ASSY, FRT BOTH DOORS, TRANSFER DOOR ASSY, CUT, WELD & RENEW FRT BOTH W/SCREEN PILLARS, FRT INNER PANEL, TOP ROOF PANEL, REINFORCEMENT & BEAM, CABIN REAR PANEL, TO BE CONTINUED	0.00	1 LA	0.00	
75 KNOCK & REPAIR FRT FLOORBOARD PANEL, REALIGN CABIN STRUCTURE INCLUDING REMOVE & REFIX, STRAIGHTEN, REPAIR & REALIGN FRT CHASSISS & CABIN POSITION	3,800.00	1 LA	3,800.00	3500
76 PUTTY & RESPRAY ON TOP ROOF PANEL, REAR PANEL, FRT BOTH DOORS, FRT PANEL & INNER PANEL, FLOORBOARD PANEL, BOTH W/SCREEN PILLARS & ALL AFFECTED AREAS	1,800.00	1 LA	1,800.00	1500
77 REMOVE & REFIX REAR TRUCK FRT GATE & RAILING, REPAIR & REALIGN REAR STRUCTURE	400.00	1 LA	400.00	320
				6,950.00

Total SS 26,173.00

Add GST @ 7% 1,832.11

Total Amount payable SS 28,005.11

For Cheng Hoe Motor Pte Ltd



AUTHORISED SIGNATURE

Can to Reg
on 9/10/20

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Company

850D

Vehicle Details

Vehicle No.:

YN651B

Vehicle to be Exported:

Yes

Intended Deregistration Date:

02 Oct 2020

Vehicle Make:

ISUZU

Vehicle Model:

NPR75UH5A

Primary Colour:

White

Manufacturing Year:

2009

Engine No.:

4HK1746253

Chassis No.:

JAANPR75H97101904

Maximum Power Output:

-

Open Market Value:

\$38,249.00

Original Registration Date:

10 Oct 2009

First Registration Date:

10 Oct 2009

Transfer Count:

0

Actual ARF Paid:

\$1,913.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

30 Sep 2024

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

5

QP Paid:

\$12,916.00

OE Rebate Amount:

\$10,318.00

Total Rebate Amount:

\$10,318.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory span (if applicable) of the vehicle.

Information contained herein is correct as at 02 Oct 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 29/09/2020 18:50
Date Of Accident 28/09/2020 13:25
Exact Location Of Accident SUNGEI KADUT STRRET 1 OUTSIDE SAMWOH CORPO P/L
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number YN651B
Insured/Policyholder
Name Of Registered Owner HONG HUAT TIMBER TRADING PTE LTD
Co Reg No 197401850D
Email Address HHTIMBER@SINGNET.COM.SG
Mobile Phone No (LOCAL) +65-96391731
Alternative Phone No OFFICE-82690171

Vehicle Particulars

Manufacturer ISUZU
Model NPR75UH5A-5.2 D (M)
Exact Purpose for which vehicle was being used at time of accident GOODS TRANSPORTATION

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

GOODS VEHICLE


Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number D19MTPCVE003199
Cover Note Number

Driver

Name of Driver CHUA YOCK SHOY
NRIC No S1217839B
Date Of Birth 15/04/1955
Occupation OUTDOOR
Date Of Driving Pass 02/12/1980
Driving Experience 39 YEARS AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96391731
Fax Number
Contact Number
Email Address NOEMAIL

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer To Police Report No : T 20200929 / 2082

DECLARATION

I/We declare that the particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: