

Mechanical Inspection Report Request

Kamaliah KAMIS (SPF) <Kamaliah_KAMIS@spf.gov.sg>

Fri 18/9/2020 12:33 PM

To: Sherwin Beh (LKK Auto) <SherwinBeh@lkkauto.com>; Naz (LKKAuto) <Naz@lkkauto.com>

Cc: Bryan Ang (LKKAuto) <bryanang@lkkauto.com>; Norhidawati AHMAD (SPF) <Norhidawati_AHMAD@spf.gov.sg>; Thabagesh JEYATHESH (SPF) <Thabagesh_JEYATHESH@spf.gov.sg>; Raziz TAHAR (SPF) <Raziz_TAHAR@spf.gov.sg>; Muhammad Afiq RAHMAT (SPF) <Muhammad_Afiq_Rahmat@SPF.gov.sg>; Syed Muhd Isa OMAR ALHABSHEE (SPF) <Syed_Muhd_Isa_Omar_Alhabshee@spf.gov.sg>

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the **12 vehicles** below: **[The ones marked in RED are deemed to be URGENT hence please EXPEDITE ON THESE REQUESTS].**

a. **Case IAFP-IB-20200917 - Mechanical Inspection of Motor Van, GBB9008K (TP/IP/32333/2020)**

On the 31 July 2020 (Friday) sometime around 12.03 p.m., the motor van was travelling on lane 1 of 3 lanes road along Jurong West Avenue 1 towards Corporation Road. Somewhere near to lamp post 56, the said motor van collided into a pedestrian who had crossed the road from the left to right from the front of a stationary motor car. The pedestrian was reported to be conscious after the accident and was conveyed to hospital by ambulance. During the stay in hospital, the pedestrian's condition deteriorated.

Vehicle to be inspected: **GBB9008K - Driver (Potential Defendant)**

IO In-Charge: DOC Jeya

b. **Case IAFP-IB-20200917 - Mechanical Inspection for Bicycle (TP/IP/25271/2020)**

c. **Case IAFP-IB-20200917 - Mechanical Inspection for Motor Van, GBE1000T (TP/IP/25271/2020)**

On 12 June 2020 (Friday) at 11.18 a.m., the Deceased who was a riding a bicycle across the carpark entrance when motor van GBE 1000 T which was travelling along the car park service road of Block 665 Yishun Avenue 4 collided into the Deceased. As a result of the accident, B2 sustained abrasions on her right hand and leg and swelling on her forehead. The Deceased refused conveyance to the hospital by was handed over to Deceased's son who was also at scene. The Deceased turned unconscious at home on the same day and was conveyed to the hospital where she was subsequently pronounced dead few days later.

Vehicle to be inspected: **Bicycle - Pedal Cyclist (Deceased)**
GBE1000T - Driver (Potential Defendant)

IO In-Charge: SIO Raziz

d. **Case IAFP-IB-20200917 - Mechanical Inspection for Motorcycle, FBN8450J (TP/IP/33609/2020)**

e. **Case IAFP-IB-20200917 - Mechanical Inspection for Motorcycle, FBA6555Y (TP/IP/33609/2020)**

On 9 August 2020 (Sunday) at 1.23 a.m., the Involved Party (who was alone on his motorcycle FBN 8450 J) was travelling along ECP towards AYE 4km on lane 1 of 3-lane road when the Deceased (who was alone on his motorcycle FBA 6555Y) collided into the rear left of the Involved Party's motorcycle. As a result of the accident, the Deceased sustained head injuries and was conveyed to the hospital where he succumbed to his injuries and was pronounced dead.

Vehicle to be inspected: **FBN8450J - Rider (Involved Party)**
FBA6555Y - Rider (Deceased)

IO In-Charge: SIO Raziz

f. **Case IAFP-IB-20200917 - Mechanical Inspection for Motorcycle, FBB5193J (TP/IP/35181/2020)**

g. **Case IAFP-IB-20200917 - Mechanical Inspection for Motorcar, SJJ9162K (TP/IP/35181/2020)**

On 18 August 2020 (Tuesday) at 4.24 p.m., the Deceased (who was riding motorcycle FBB 5193 J with a pillion, 2nd Deceased) was travelling along TPE (SLE) 5.5km on lane 4 of 4-lane road when the Deceased suddenly veered to the right into lane 2 of 4-lane road and collided into left front portion Involved Party who was driving motorcar SJJ 9162 K . As a result of the accident, the Deceased and 2nd Deceased sustained sustained multiple injuries and were pronounced dead at scene.

Vehicle to be inspected: **FBB5193J** - Rider (Deceased)
 SJJ9162K - Driver (Involved Party)

IO In-Charge: SIO Raziz

h. **Case IAFP-IB-20200917 - Mechanical Inspection of Motorcycle, FBK1067U (TP/IP/38511/2020)**

On 7 September 2020 (Monday) at about 8.23 a.m., the rider of motorcycle FBK1067U (B1) was travelling along Ubi Avenue 1 towards Ubi Road 1 when he was tap on his brakes and skidded. B1 claimed there was mechanical fault to the brakes which resulted in the accident.

Vehicles to be inspected: **FBK1067U** - Rider (Involved Party)

IO In-Charge: IO Afiq

i. **Case IAFP-IB-20200917 - Mechanical Inspection for Motorcycle, FBE3293B (TP/IP/26679/2020)**

On 21 June 2020 (Sunday) at 10.57 p.m., based on a video footage retrieved from a nearby PowerGrid Terminal , it revealed that the motorcyclist was travelling alone on his motorcycle along Tuas South Avenue 9 towards End on lane 3 of 3-lane road before another camera angle captured and partially showed the motorcycle ending up on the grass patch. There was no other vehicle travelling together, alongside with the motorcyclist. As a result of the accident, the motorcyclist sustained haematoma on the top right of his head, abrasions on his right knee and suspected to sustain spinal injury in an unconscious state. He was intubated and sent in for CT scan and surgery. The motorcyclist is currently in the ICU at National University Hospital.

Vehicle to be inspected: **FBE3293B** - Rider (Involved Party)

IO In-Charge: IO Syed Isa

j. **Case IAFP-IB-20200917 - Mechanical Inspection for Motor Van, GZ4386R (TP/IP/39781/2020)**

On 14 September 2020 (Monday) sometime before 11.17 a.m., based on a video footage retrieved from the Accused's motor van, the Accused was exiting Parkway East Hospital and subsequently made a right turn into lane 1 of 2-lane road of Telok Kurau Road towards Marine Crescent. While negotiating the right turn, the front centre portion of the Accused's motor van was seen colliding onto the Deceased's right side while the Deceased was still walking with her walking stick and crossing the road ahead of the Accused's motor van, from the Accused's left side to right side. Due to the impact, the Deceased fell backwards and hit her head on the road, on lane 1 of 2-lane road of Telok Kurau Road towards Marine Crescent. As a result of the accident, the Deceased sustained skull fracture and multiple abrasions hence she was conveyed to Changi General Hospital (CGH) by an ambulance. However on 15 September 2020 (Tuesday) at 12.28 a.m., the Deceased succumbed to her injuries and was pronounced dead by Dr Ang Jie in CGH Ward No. 33, Bed No. 17.

Vehicle to be inspected: **GZ4386R** - Driver (Potential Defendant)

IO In-Charge: SIO Kamaliah

k. Case IAFP-IB-20200917 - Mechanical Inspection for Motorcycle, FBL6399Z (TP/IP/36003/2020)

l. Case IAFP-IB-20200917 - Mechanical Inspection for Motor Van, QX4820X (TP/IP/36003/2020)

On 23 August 2020 (Sunday) at about 10.45 p.m., video footages from LTA junction eye and POLCAM revealed that the motorcycle was travelling straight along Aljunied Road towards Guillemard Road on centre lane of 3-lane road. At this juncture, the motor van was travelling along Aljunied Road towards Macpherson Road on lane 1 of the 3-lane road and subsequently made a right turn from Aljunied Road into Sims Avenue. While the motor van was making the right turn, it collided into the motorcycle that had just entered the signalised cross junction.

Vehicle to be inspected: **FBL6399Z** - Rider (Involved Party)
 QX4820X - Driver (Potential Defendant)

IO In-Charge: SIO Kamaliah

2. These request has been approved by my management.

3. Thank you Sirs.

cc: DOC Jeya, SIO Raziz, IO Afiq and IO Syed Isa, as requested by you
 Bryan & OC Wati, fyp

Best regards,

Kamaliah Kamis (Miss)

Senior Investigation Officer | Fatal Accident Investigation Team

Traffic Police Department | Singapore Police Force

DID: (65) 6547 6435 | FAX: (65) 6547 6352



Singapore Police Force – *Commemorating 200 Years of Policing*

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."