



創 CHARN'S CUSTOMCRAFT

*Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars*

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

FWD/FC(SHD3200D)

DOA: 05/10/2020@1500

MS FIRST CAPITAL INSURANCE PTE LTD

09/10/2020

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SCR 8831 K - TOYOTA WISH 1.8 CVT

CHASSIS NO: JTDGG20W90J003645 (2016)

1 pc	Rear bumper retainer	\$ 45.00
1 pc	Rear bumper	\$ 240.00
		<u>\$ 285.00</u>
	Remove necessary parts: jacking, panel beating, repair and straighten front fender LH inclusive replacing the above.	\$ 200.00
	Putty and respray rear fender LH and rear bumper.	\$ 400.00
		<u>\$ 885.00</u>
	ADD 7% GST	\$ 61.95
		<u><u>\$ 946.95</u></u>

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....
