

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933







NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref:	NS/INC20011182/Esd3e2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date:	03-11-2020		
4	Dalian Bartianlara	Code:	INC4		
1.	Policy Particulars :- THIRD PARTY CLAIM  Insured Veh. SLT 4837D Veh. Inspected SHC 8445L				
Policy No.	5111567344-01	Coverage (\$)		0.00	
Claim No.	MT/1106717-002	Excess (\$)		0.00	
Assign From	W171100717 002	Assign		15/10/2020	
2.	recognition (including the control of the control o				
Make & Model	HYUNDAI I40	c.c	Condition	1685	
Engine No.	HIDDEN	Year o	f Rea.	2015	
Chassis No.	KMHLB41UMGU080635	Colour		BLUE	
Odometer	565131	Steering		IN ORDER	
Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
General	FAIR				
3. Conditions of Tyres					
	Size	Make		Balance	
R/H Front Tyre	205/60 R16	MICHE	LIN	5 mm	
L/H Front Tyre	205/60 R16	MICHE	LIN	5 mm	
R/H Rear Tyre	205/60 R16	MICHE	LIN	5 mm	
L/H Rear Tyre	205/60 R16	MICHE	LIN	5 mm	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
DAMAGES SEE DETAILS.					
5. General Information					
Accident Date	14/10/2020	Inspec	tion Date	15/10/2020	
Survey held at	Survey held at COMFORTDELGRO ENGINEERING PTE LTD  59 LOYANG DRIVE SINGAPORE 508969				
5a. Remarks					
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				