



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III20004585/Qtf3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 20-10-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3523C	Veh. Inspected	SKS 7150Z
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT20030312	Excess (\$)	0.00
Assign From	CARINE KEK PHER SER	Assign Date	15/10/2020

2. Vehicle Particulars & Condition

Make & Model	MAZDA3 4-DOOR	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6BM42A8G0307231	Colour	RED
Odometer	160082	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	MICHELIN	6 mm
L/H Front Tyre	205/60 R16	MICHELIN	6 mm
R/H Rear Tyre	205/60 R16	MICHELIN	6 mm
L/H Rear Tyre	205/60 R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/03/2020	Inspection Date	27/03/2020
Survey held at	REVOL CARZ GARAGE PTE LTD BLOCK 10, ANG MO KIO IND PARK 2A #02-18, AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------