

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0768/2020/NS
DATE : 13-Oct-20
WIP : 53053

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR DARA ROK ING
ADDRESS : BLK 440 CHOA CHU KANG AVENUE 4
#06-457
SINGAPORE 680440
TELEPHONE : HP +65 87155938
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070006889
VEHICLE NO : **SMR 8970 Z**
MODEL CODE : AUDI A5 SPORTSBACK 2.0 TFS
MODEL YEAR : 30/1/2020
ENGINE NO : CVK 087014
CHASSIS NO : WAUZZZF59KA073043
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Oct-20
PLACE OF ACCIDENT : INTERSECTION CHOA CHU KANG AVE 4
AND CHOA CHU KANG WAY


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 8970 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 280.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓	\$ 1,750.00	500
4	TO RESPRAY FRONT BUMPER AND BONNET. ✓	\$ 1,650.00	8550
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,272.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 8970 Z

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>not in Regis</i>		\$ 2,251.00	+
2 FRONT BUMPER FIXING PARTS		\$ 402.00	+
3 FRONT BUMPER GRILLE - CENTRE		\$ 194.00	+
4 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 225.00	+
5 FRONT BUMPER SPOILER		\$ 529.00	+
6 RADIATOR GRILLE <i>could</i>		\$ 2,300.00	✓
7 ULTRASOUND SENSOR SUPPORT - LH <i>new</i>	2	\$ 102.00	+
8 RADIATOR GRILLE COVER - UPPER		\$ 187.00	+
9 FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>		\$ 468.00	+
10 FRONT BUMPER FOAM FILLER PIECE		\$ 123.00	+
11 FRONT BUMPER CARRIER		\$ 795.00	+
12 FRONT BUMPER TOP COVER <i>new</i>		\$ 126.00	+
13 LOCK CARRIER BRACKET		\$ 136.00	+
14 LOCK CARRIER BRACKET SUPPORT - LH / RH <i>new</i>	2	\$ 56.00	+
15 CAUTION SIGN STICKER <i>not new</i>	NEC	\$ 14.00	+
16 AIRCON STICKER <i>not new</i>	NEC	\$ 8.00	+
17 FRONT PARKING AID SENSOR - INNER <i>new</i>		\$ 242.00	+
18 FRONT PARKING AID SEAL RING	4	\$ 14.00	+
19 BONNET IMPACT PROTECTION - CENTRE <i>new</i>		\$ 27.00	+
20 BONNET IMPACT PROTECTION - LH		\$ 28.00	+
SUB TOTAL SPARE PARTS	:	\$ 8,227.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 8970 Z

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 BONNET IMPACT PROTECTION - RH		\$ 27.00	+
22 LED HEADLIGHT - LH		\$ 7,812.00	+
23 FRONT NO PLATE	S/N	\$ 60.00	✓
24 SUNDRIES		\$ 250.00	?
TOTAL SPARE PARTS	:	\$ 16,376.00	
TOTAL LABOUR CHARGES	:	\$ 4,272.00	
GRAND TOTAL	:	\$ 20,648.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
SURVEYED DATE : *15/10/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT