



萬 春 摩 哆

BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GST Reg. No. 351915/00A

GST Regn No. 35191500A

15/10/2020

MS First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

Attn: Motor Claims Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. XE 4515 U
MODEL: MAN TGS 32.360
DATE OF ACCIDENT: 14/10/2020
YOUR INSURED VEHICLE NO. SHA 312 A

1 pc	Rear bumper	\$	850.00	SN
1 pc	Rear number plate		30.00	SN
1 pc	60km/hr sticker		20.00	SN
1 pc	DANGER HIGHLY FLAMMABLE sticker		180.00	SN
		\$	<u>1,080.00</u>	

LABOUR CHARGES:

To knocking and straightening of all necessary damaged parts.

To changing of the above parts.

To putty and spray painting on accident damaged parts.

400.00
400.00
<u>\$ 1,880.00</u>

Yours faithfully,

Redindo