

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

15-Oct-20 16/10/20, 9.30 AM  
CO. REG:200707743D GST REG:200707743D

4 days, My AL sy, L/S  
**ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6250 U**

|          |                                                |       |             |
|----------|------------------------------------------------|-------|-------------|
| 1 pc     | Front o/s door moulding outer                  | X nn  | \$ 73.00    |
| 1 pc     | Front o/s fender                               | / DD  | \$ 384.00   |
| 1 pc     | Front o/s fender inner shield                  | X nn  | \$ 120.00   |
| 2 pcs    | Front bumper n/s & o/s side retainer @ \$16.00 | X nn  | \$ 32.00    |
| 1 pc     | o/s mirror assy                                | X nn  | \$ 590.00   |
| 1 pc     | Front bumper                                   | X nn  | \$ 531.00   |
| 1 pc     | Front o/s door                                 | / DD  | \$ 761.00   |
| 2 pcs    | Front o/s door hinges @ \$34.00                | X svc | \$ 68.00    |
| 1 pc     | Rear o/s door                                  | X R   | \$ 791.00   |
| 2 pcs    | Rear o/s door hinges @ \$34.00                 | X svc | \$ 68.00    |
| 1 pc     | o/s rocker panel garnish                       | X R   | \$ 286.00   |
| 2 pcs    | Front o/s & Rear o/s wheel cover @ \$116       | X svc | \$ 232.00   |
| 1 pc     | Rear bumper o/s side bracket                   | X nn  | \$ 29.00    |
| 1 pc     | Rear bumper                                    | X nn  | \$ 696.00   |
|          |                                                |       | \$ 2,931.00 |
| Less 10% |                                                |       | \$ 293.10   |
|          |                                                |       | \$ 2,637.90 |

## S/NETT

|                                                                                                                                                                                                         |                                     |      |                  |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------|------|------------------|
| 1 set                                                                                                                                                                                                   | o/s rocker panel garnish clips      | X nn | \$ 38.00         |
| 1 set                                                                                                                                                                                                   | o/s door stickers                   | / NP | \$ 100.00 80     |
| 1 pc                                                                                                                                                                                                    | Rear o/s fender sticker             | / NP | \$ 60.00 30      |
| 1 pc                                                                                                                                                                                                    | Rear bumper clips                   | X nn | \$ 48.00         |
| 1 pc                                                                                                                                                                                                    | Front o/s fender sticker            | / NP | \$ 30.00 10      |
| 1 set                                                                                                                                                                                                   | Front o/s fender inner shield clips | X nn | \$ 28.00         |
| Sundry                                                                                                                                                                                                  |                                     |      | \$ 50.00 30      |
| To check for rear & rear o/s wheel alignment                                                                                                                                                            |                                     |      | \$ 80.00 X       |
| To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.                                                                                  |                                     |      | \$ 180.00 X      |
| To refit inner components of the front & rear o/s doors onto new shell doors                                                                                                                            |                                     |      | \$ 300.00 X 50   |
| To labour charge for dismantle and renew the accident damaged parts. To heat/wled & cut rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the front o/s door pillar, etc. |                                     |      | \$ 1,600.00 500  |
| To putty and spray painting on front o/s door, front o/s door pillar, rear o/s door, o/s rocker panel garnish, rear o/s fender, rear bumper, front bumper, o/s mirror cover, front o/s fender           |                                     |      | \$ 1,800.00 1000 |
| To apply rustproofing on the repaired and replaced panels.                                                                                                                                              |                                     |      | \$ 180.00 30     |
|                                                                                                                                                                                                         |                                     |      | \$ 11,667.00     |

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )