

EROFIA MOTOR TRADING PTE LTD

INDIA

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Name : Victor Rajesh Naidu

Accident Date : 10-Oct-20

Vehicle No : FBL797Y

Kymco
Vehicle Model : Downtown
200I

Estimated Repair Costs

Qty	Description	Amount S(\$)
	List Items	
1	Front fork assy	800 \$ 1,300.00 X
1	Front fender	2 \$ 220.00 X
1	Front centre lower cover	cu7 \$ 180.00 ✓
1	Rear side fairing R/H	2 \$ 260.00 X
1	Front fairing	cu7 \$ 280.00 ✓
1	Centre side cover - R/H	cu7 \$ 160.00 ✓
1	Brake lever - R/H	cu7 \$ 65.00 ✓
1	Balancer - R/H	cu7 \$ 50.00 ✓
1	Mirror - R/H	800 \$ 160.00 X
1	Handle-bar	2 \$ 170.00 X
1	Exhaust pipe assy	cu7 \$ 985.00 X
1	Exhaust cover	cu7 \$ 170.00 ✓
1	Exhaust end cover	cu7 \$ 120.00 ✓
		\$ 4,120.00
Less 10%		\$ 412.00
		\$ 3,708.00

Special Nett Items

1	Bearing cone (1 set)	11 \$ 120.00 X
		\$ 120.00

S/No. Labour

1	To provide towing	\$ 11 80.00 X
2	To check wiring and reset headlamp focusing	\$ 11 80.00 X
3	To respray painting	380 \$ 600.00
4	To provide labour	250 \$ 480.00
		\$ 1,240.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Grand Total

\$ 5,068.00

Singapore Dollars: Five Thousand and Sixty-Eight only

[Signature]

Acknowledged by Repairer

Signature:

P- 970
1/2
873
1503
mr.

EROFIA MOTOR TRADING PTE LTD