

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 27 Oct 2020

## **Preliminary Advice**

Insured Vehicle No	: S5367CD	Accident Date	: 02/10/2020
TP Vehicle No	: SMU7545J	Assignment Date	: 16/10/2020
Make	: MERCEDES-BENZ GLC300	Est. Duration of Repair	: 2 days
Date of Inspection	: 19/10/2020		
Inspection At	: TTS Eurocars Pte Ltd (Sin Ming) 383 Sin Ming Drive, TTS Centre Singapore 575717		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,052.26
Revised Amount	:S\$	859.36
Check Items (Estimated)	:S\$	656.23
Total	:S\$	1,515.59

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : TP : WP