

LOH HENG

Automotive Repair Services
Accident Insurance Claims

13/10/2020

EQ INSURANCE PTE LTD

Attn. : Motor Claim Department

Re : Estimated Quotation

Vehicle No. : ~~SIN 9948L~~ Toyota Wish

SIN 8576K

Not Authorized
Ling B
Paying After Paint

6 days

S/N	Description	Amount (\$)
A	PART REPLACEMENT	
	Front bonnet	\$ 887.50
	Bonnet chrome moulding	\$ 228.90
	Front bonnet lock	\$ 104.60
	Front bonnet hinge right	\$ 74.60
	Front bonnet hinge left	\$ 74.60
	Bonnet cable	\$ 58.70
	Front bumper	\$ 601.90
	Front bumper retainer (right and left) \$87x2	\$ 174.00
	Front bumper grill	\$ 274.10
	Front bumper reinforcement	\$ 547.00
	Panel garnish clips 10 pcs	\$ 40.00
	Front bumper spone	\$ 128.40
	Front bumper garnish	\$ 93.00
	Brace panel front	\$ 189.50
	Headlamp right	\$ 1,214.60
	Headlamp left	\$ 1,214.60
	Front support panel	\$ 1,325.30
	Radiator	\$ 1,685.00
	Air con fan motor	\$ 375.00
	Radiator fan motor	\$ 375.00
	Radiator cowl	\$ 241.00
	Radiator top garnish	\$ 123.70
	Air con condenser	\$ 1,980.60
	Air con discharge pipe	\$ 394.10
	Air con liquid pipe	\$ 547.00
	Air con suction pipe	\$ 375.00
		\$ 13,327.70
	less 25%	
	sub total	\$ 9,995.25
B	No plate with casing (nett)	\$ 60.00
1	LABOUR CHARGES	
2	To remove and replace new parts, restrengthen inner chasis, front support panel, lower panel. Realignment body structure.	\$ 1,100.00

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384

Automotive Repair Services
Accident Insurance Claims

3	To remove and replace air-con condenser, refill air-con gas	\$ 200.00
4	Remove and replace wiring harness	\$ 550.00
5	To respray + putty on damaged parts	\$ 1,100.00
6	Towing to workshop	\$ 60.00
7		
8	Under coating after repair	\$ 150.00
	GRAND TOTAL OF A & B	\$ 13,215.25

1001
X9001
501
601

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384