



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 09/10/2020
TP Veh Reg No: SMD4758X

Estimate No: ES2000091
Date: 16 Oct 2020
Policy No:
Veh Reg No: FBR751Y
Make/Model: YAMAHA MT15
MANUAL
Chassis No: MH3RG5610KK004688
Engine No: G3K9E0029555
Reg. Date: 17/02/2020

Estimate Repair Cost to Vehicle No :FBR751Y

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
35 WING MIRROR - RH	144.00	1 PC	<i>nd</i> 144.00	✓
36 HANDLE BAR BRACKET	180.00	1 PC	<i>R</i> 180.00	✓
37 FRONT FORK HOLDER BRACKET	380.00	1 PC	<i>dit</i> 380.00	✓
38 FRONT HANDLE BAR	320.85	1 PC	<i>R</i> 320.85	✓
39 REAR CARRY BOX	495.85	1 PC	<i>nd/m</i> 495.85	✓
40 REAR CARRY BOX BRACKET	220.15	1 PC	<i>R</i> 220.15	X
41 REAR NUMBER PLATE HANDLE	260.15	1 PC	<i>dit</i> 260.15	✓
			8,213.80	8,213.80
Labour				
42 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	800.00	1 JOB	800.00	<i>1800</i>
43 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	700.00	1 JOB	700.00	<i>nn</i> ✓
44 TO ALIGN MAIN BODY FRAME.	280.00	1 JOB	280.00	<i>1200</i>
45 TO TOW VEHICLE TO WORKSHOP.	50.00	1 JOB	50.00	<i>300</i>
			1,830.00	1,830.00
Total				S\$ 10,093.80
Add GST @ 7%				706.57
Total Amount Payable				S\$ 10,800.37

TOTAL: SINGAPORE DOLLAR TEN THOUSAND EIGHT HUNDRED AND CENTS THIRTY SEVEN ONLY

For Yee Auto Pte Ltd


AUTHORISED SIGNATURE