

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20011238/UGA3Q2

Date: 16/02/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MPC0000620
Claimant Vehicle No : SMH6712T **Insured Vehicle No :** SMC6749P
 Date of Loss: 12/10/2020 Nature of Claim: TP Claim No: MPC2020D0002070

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH6712T**
 Make & Model: HONDA CIVIC, 1.5 (A) Engine No: L15C1011952
 Reg. Date: 29/01/2019 (Man. Year: 2018) Chassis No: FK71011922
 Colour: Black Odometer: 88496 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
 Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
 Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,610.08	2,188.72	421.36	16.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	1,050.00	570.00	35.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,230.08	3,238.72	991.36	23.44
Approved Total (Overridden) (S\$)		2,550.00		
(S\$)	4,230.08	2,550.00	1,680.08	39.72
+ GST 7.00/7.00% (S\$)	296.11	178.50	117.61	39.72
Nett Amount (S\$)	4,526.19	2,728.50	1,797.69	39.72
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		3,259.50		

INSPECTION

Date of Assignment: 16/10/2020
 Date Inspected: 19/10/2020 Inspected At: Focus Auto Pte Ltd (Kaki Bukit)
 Estimated Period of Repair: 4.0 days NO 1 KAKI BUKIT AVE 6(AUTOBAY) #02-50
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2021)
Parts:	143	HONDA CIVIC 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH6712T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER -LH	Badly Dented	336.00 FL	*336.00 FL
2	1		*FRONT FENDER DIST COVER-LH	Torn	148.50 FL	*148.50 FL
3	1		*SET FRONT FENDER DUST COVER CLIPSE -LH	Necessary	33.00 FL	*33.00 FL
4	1		*FRONT FENDER LAMP -LH	Scratched	126.20 FL	*126.20 FL
5	1		*FRONT HEADLAMP -LH	Cracked	690.70 FL	*690.70 FL
6	1		*FRONT HEADLAMP FOR GARNISH -LH	Repair	89.20 FL	*- FL
7	1		*FRONT BUMPER	Torn	579.90 FL	*579.90 FL
8	1		*FRONT BUMPER SIDE RETAINER -LH	Bent	50.40 FL	*50.40 FL
9	1		*FRONT BUMPER FOG LAMP COVER -LH	Cut / Cracked	146.20 FL	*146.20 FL
10	1		*FRONT BUMPER LOWER SPOILER	Torn	850.00 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,050.10	2,610.90
- List Item Discount on L Items 20.00/20.00% (S\$)	440.02	422.18
Total Parts (S\$)	2,610.08	2,188.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	400.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	30.00
4	SPRAY PAINTING	New	700.00	600.00
Gross Labour Cost (S\$)			1,620.00	1,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >