



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## Supplementary Estimate 2

GST Reg No. 19-9902271-W

**AIG Asia Pacific Insurance Pte Ltd**  
 78 Shenton Way  
 #07-16 AIG Building  
 Singapore 079120  
**Attn: Mr. Adrian Ling - Motor Claims Dept**  
**Tel: 6841 0055 - Fax: 6256 4315**

**Estimate No.**  
**Date**  
**Service Advisor**  
**Pages**  
**Regn No**  
**Model No**

PA/OD/0777/2020/NS  
 31-Oct-20  
 George Wong  
 1  
 SMR 296 R  
 Audi A3 Sedan 1.0 TFSI

| Quantity      | Description                                                      |     | Unit Price         | Amount |
|---------------|------------------------------------------------------------------|-----|--------------------|--------|
| <b>LABOUR</b> |                                                                  |     |                    |        |
| 1             | To remove and renew rear exhaust silencer and align to position. | S/N | \$ 480.00          | ✓      |
| <b>PART</b>   |                                                                  |     |                    |        |
| 1             | REAR SILENCER <i>Bent</i>                                        |     | \$ 677.00          | ✓      |
| 2             | REAR SILENCER DUAL CLIP <i>Rec</i>                               |     | \$ 55.00           | ✓      |
| 3             | REAR SILENCER EXHAUST SYSTEM <i>But</i>                          |     | \$ 77.00           | ✓      |
| 2             | KEYLESS CONTROL UNIT <i>Rec</i>                                  |     | \$ 69.00           | ✓      |
| 3             | REAR WHEEL HOUSING LINER ADAPTER-RH <i>cuple</i>                 |     | \$ 37.00           | ✓      |
| 4             | CONNECTING PLATE-LH/RH <i>RH installed</i>                       | 2   | \$ 286.00          | 143    |
| <b>TOTAL</b>  |                                                                  |     | <b>\$ 1,681.00</b> |        |

For Premium Automobiles Pte Ltd

Authorised Signature

*Adrian Ling*  
 02/10/20  
*[Signature]*

Car-in 16/10/2020 wip: 51718 (LHS) / 54037 (RHS)

# PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Kiam/Hong



## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 296 P

| S/N PARTS DESCRIPTION                             | QTY    | DAMAGED PARTS & PRICES<br>S/NETT | REMARKS |
|---------------------------------------------------|--------|----------------------------------|---------|
| 1 FRONT BUMPER <i>new</i>                         | \$     | 1,987.00                         | +       |
| 2 FRONT BUMPER FIXING PARTS                       | \$     | 185.00                           | +       |
| 3 FRONT BUMPER GUIDE SECTION - LH <i>new</i>      | \$     | 38.00                            | +       |
| 4 <u>FRONT FENDER - LH</u> <i>Dented</i>          | \$     | 841.00                           | ✓       |
| 5 FRONT FENDER ATTACHMENT PARTS <i>new</i>        | \$     | 71.00                            | +       |
| 6 FRONT FENDER BRACKET - LH <i>new</i>            | \$     | 38.00                            | +       |
| 7 FRONT FENDER BRACE - LH <i>new Best</i>         | \$     | 95.00                            | ✓       |
| 8 FRONT WHEEL HOUSING LINER - LH <i>new</i>       | \$     | 167.00                           | +       |
| 9 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i> | \$     | 88.00                            | +       |
| 10 LED HEADLIGHT - LH <i>new</i>                  | \$     | 5,455.00                         | +       |
| 11 <u>FRONT DOOR - LH</u> <i>Dented</i>           | \$     | 2,494.00                         | ✓       |
| 12 <u>FRONT DOOR OUTER SEAL</u> <i>new</i>        | NEC \$ | 159.00                           | ✓       |
| 13 BONDING AGENT ?                                | NEC \$ | 47.00                            | ?       |
| 14 CLEANING SOLUTION ?                            | NEC \$ | 65.00                            | ?       |
| 15 FRONT DOOR ATTACHMENT PARTS <i>new</i>         | \$     | 238.00                           | +       |
| 16 FRONT DOOR CATCH ?                             | \$     | 104.00                           | ?       |
| 17 <u>REAR DOOR - LH</u> <i>Dented</i>            | \$     | 2,494.00                         | ✓       |
| 18 <u>REAR DOOR OUTER SEAL</u> <i>new</i>         | NEC \$ | 159.00                           | ✓       |
| 19 BONDING AGENT ?                                | NEC \$ | 47.00                            | ?       |
| 20 CLEANING SOLUTION ?                            | NEC \$ | 65.00                            | ?       |
| <b>SUB TOTAL SPARE PARTS</b>                      | :      | <b>\$ 14,837.00</b>              |         |

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 296 P

| S/N PARTS DESCRIPTION                                | QTY | DAMAGED PARTS & PRICES |           | REMARKS |
|------------------------------------------------------|-----|------------------------|-----------|---------|
|                                                      |     | S/NETT                 |           |         |
| 21 REAR DOOR ATTACHMENT PARTS <i>Ren</i>             |     | \$                     | 127.00    | +       |
| 22 REAR DOOR CATCH ?                                 |     | \$                     | 93.00     | 7       |
| 23 <del>SIDE FRAME - LH</del> <i>Dented</i>          |     | \$                     | 3,436.00  | —       |
| 24 REAR WINDSCREEN <i>Ren</i>                        |     | \$                     | 805.00    | —       |
| 25 <del>SIDE WINDOW - LH</del> <i>Ren</i>            |     | \$                     | 563.00    | —       |
| 26 PRIMER <i>Ren</i>                                 |     | \$                     | 19.00     | —       |
| 27 REAR FENDER - RH <i>Buckled</i>                   |     | \$                     | 2,305.00  | —       |
| 28 <del>SIDE WINDOW - RH</del> <i>Ren</i>            |     | \$                     | 563.00    | —       |
| 29 REAR BUMPER <i>Distorted</i>                      |     | \$                     | 1,944.00  | —       |
| 30 REAR BUMPER FIXING PARTS <i>Ren</i>               |     | \$                     | 191.00    | x.      |
| 31 REAR BUMPER GUIDE SECTION - LH / RH <i>RH Dgd</i> |     | \$                     | 32.00     | 16.     |
| 32 REAR BUMPER LOCKING MECHANISM <i>dayd</i>         | 2   | \$                     | 59.00     | ✓       |
| 33 REAR BUMPER SPOILER <i>Dented</i>                 |     | \$                     | 234.00    | —       |
| 34 REAR LIGHT REFLECTOR - LH / RH <i>RH cracked</i>  | 2   | \$                     | 82.00     | 41.     |
| 35 LED TAIL LIGHT / RH <i>RH ut</i>                  | 2   | \$                     | 1,734.00  | 867.    |
| 36 TAIL LIGHT TRIM - LH / RH <i>RH ut</i>            | 2   | \$                     | 60.00     | 30      |
| 37 LED TAIL LIGHT - LH / RH <i>RH ut</i>             | 2   | \$                     | 1,734.00  | 867.    |
| 38 TAIL LIGHT TRIM - LH / RH <i>Ne Ren</i>           | 2   | \$                     | 60.00     | +       |
| 39 LED LICENSE PLATE LIGHT <i>Ren</i>                | 2   | \$                     | 197.00    | +       |
| 40 REAR BUMPER REINFORCEMENT BEAM <i>Bent</i>        |     | \$                     | 565.00    | ✓       |
| SUB TOTAL SPARE PARTS                                |     | \$                     | 14,803.00 |         |

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 296 P

| S/N PARTS DESCRIPTION                                          | QTY | DAMAGED PARTS & PRICES<br>S/NETT | REMARKS |
|----------------------------------------------------------------|-----|----------------------------------|---------|
| 41 REAR BUMPER BRACKET - LH <i>Dmgd</i>                        |     | \$ 27.00                         | ✓       |
| 42 REAR BUMPER BRACKET - RH ?                                  |     | \$ 28.00                         | ?       |
| 43 REAR BUMPER GUIDE SECTION - LH / RH <i>Cracked</i>          | 2   | \$ 132.00                        | 66      |
| 44 REAR PARKING AID SENSOR - INNER / OUTER <i>1 piece dmgd</i> | 4   | TBC                              |         |
| 45 REAR PARKING AID SEAL RING <i>new</i>                       | 4   | \$ 14.00                         | -       |
| 46 REAR BUMPER WIRING SET <i>new</i>                           |     | \$ 510.00                        | +       |
| 47 REAR CROSS PANEL <i>Dented</i>                              |     | \$ 356.00                        | ✓       |
| 48 REAR CROSS PANEL REINFORCEMENT <i>Dented</i>                |     | \$ 725.00                        | ✓       |
| 49 REAR LID <i>Dented</i>                                      |     | \$ 2,564.00                      | ✓       |
| 50 REAR LID ATTACHMENT PARTS <i>new</i>                        |     | \$ 291.00                        | +       |
| 51 REAR LID HINGE - LH / RH <i>new</i>                         | 2   | \$ 506.00                        | 253     |
| 52 REAR LID FLAP GASKET <i>new</i>                             |     | \$ 203.00                        | +       |
| 53 REAR LID LOCK STRIKER <i>new</i>                            |     | \$ 49.00                         | +       |
| 54 REAR LID LOCK <i>new</i>                                    |     | \$ 184.00                        | +       |
| 55 PACKING ADHESIVE <i>new</i>                                 |     | \$ 18.00                         | ✓       |
| 56 REAR LID LOCK ACTUATOR <i>new</i>                           |     | \$ 1,330.00                      | ✓       |
| 57 AUDI EMBLEM <i>new</i>                                      |     | \$ 122.00                        | -       |
| 58 A3 INSCRIPTION <i>new</i>                                   |     | \$ 95.00                         | -       |
| 59 REAR LID TRIM PANEL <i>new</i>                              |     | \$ 303.00                        | +       |
| 60 REAR CROSS PANEL TRIM ?                                     |     | \$ 153.00                        | ?       |
| SUB TOTAL SPARE PARTS                                          |     | \$ 7,610.00                      |         |

Resubmited 02/11/20

Adrian

*[Signature]*