



ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0777/2020/NS  
DATE : 2-Oct-20  
WIP : 51718

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

**hi Adrian****20 days exclude 3 Sundays 2 PH****Johnny Boo****ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT****TEL: 6841 0055 - FAX: 6256 4315**

OWNER'S NAME : MS QIN XIANG  
ADDRESS : 33 PASIR RIS DRIVE 3  
#05-04  
SINGAPORE 519492  
TELEPHONE : HP +65 83037290  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1900256402  
VEHICLE NO : **SMR 296 P**  
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V  
MODEL YEAR : 14/12/2019  
ENGINE NO : CHZ C35258  
CHASSIS NO : WAUZZZ8V0LA002554  
MILEAGE : 12416KM  
DATE IN : 2-Oct-20  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 2-Oct-20  
PLACE OF ACCIDENT : DECATHLON BEDOK CARPARK D

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 296 P**

| S/N                             | NATURE OF JOBS                                                                              |        | ESTIMATED<br>CHARGES |           | SURVEYOR'S<br>RECOMMENDATIONS |
|---------------------------------|---------------------------------------------------------------------------------------------|--------|----------------------|-----------|-------------------------------|
| 1                               | TO PLACE VEHICLE ON CAR O-LINER.                                                            | S/N \$ | 1,800.00             | \$        | <b>1,800.00</b>               |
| 2                               | TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER.                                         | S/N \$ | 800.00               | \$        | <b>800.00</b>                 |
| 3                               | TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.     | S/N \$ | 280.00               | \$        | <b>280.00</b>                 |
| 4                               | TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS. | S/N \$ | 280.00               | \$        | <b>280.00</b>                 |
| 5                               | TO RENEW RHS <b>REAR 1/4 GLASS</b> TO FACILITATE FENDER RENEWAL.                            | S/N \$ | 900.00               | \$        | <b>300.00</b>                 |
| 6                               | TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND BOTH REAR 1/4 GLASS.                          | S/N \$ | 400.00               | \$        | <b>200.00</b>                 |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                             | :      | <b>\$ 4,460.00</b>   | <b>\$</b> | <b>3,660.00</b>               |



TEL : 6366 2323 FAX : 6841 1183



| S/N                  | NATURE OF JOBS                                                                                                                                                                                                                                                                   |            | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|----------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-------------------|----------------------------|
|                      |                                                                                                                                                                                                                                                                                  | <i>c/f</i> |                   | \$ 3,660.00                |
| 7                    | TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.                                                                                                                                                                                                                             | S/N        | \$ 200.00         | O/S                        |
| 8                    | TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.                                                                                                                                                   | S/N        | \$ 1,400.00       | O/S                        |
| 9                    | TO DISLODGE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.                                                                                                                    | S/N        | \$ 1,400.00       | O/S                        |
| 10                   | TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND WELD BOTH REAR FENDERS, LHS SILL PANEL AND REAR END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.                                                                                |            | \$ 10,000.00      | \$ 4,750.00                |
| 11                   | TO RESPRAY REAR BUMPER, REAR LID, LHS REAR FENDER, RHS REAR FENDER, DOOR ENTRANCES, LHS SILL PANEL, RHS SILL PANEL, ROOF CHANNELS, DRAIN PANELS, LHS B PILLAR, END PANELLING, REAR LID HINGES AND SPARE WHEEL HOUSING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS. |            | \$ 7,800.00       | \$ 3,850.00                |
| 11A                  | ADDED LABOUR                                                                                                                                                                                                                                                                     | S/N        | \$ 480.00         | \$ 480.00                  |
| 12                   | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                                                                                                                   | S/N        | \$ 192.00         | \$ 192.00                  |
| TOTAL LABOUR CHARGES |                                                                                                                                                                                                                                                                                  | :          | \$ 25,932.00      | \$ 12,932.00               |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 296 P**

| S/N PARTS DESCRIPTION        |                                         | QTY         | DAMAGED PARTS & PRICES |                  | REMARKS            |
|------------------------------|-----------------------------------------|-------------|------------------------|------------------|--------------------|
|                              |                                         |             | S/NETT                 |                  |                    |
| 1                            | REAR WINDSCREEN                         |             | \$                     | 805.00           |                    |
| 3                            | PRIMER                                  |             | \$                     | 19.00            | \$ 14.96           |
| 4                            | REAR FENDER - RH                        |             | \$                     | 2,305.00         | \$ 1,844.00        |
| 5                            | SIDE WINDOW - RH                        |             | \$                     | 563.00           | \$ 450.40          |
| 6                            | REAR BUMPER                             |             | \$                     | 1,944.00         | \$ 1,555.20        |
| *** 7                        | <b>REAR BUMPER REINFORCEMENT</b>        | <b>Bent</b> | \$                     | 191.00           | \$ 451.60 (A)      |
| 8                            | REAR BUMPER GUIDE SECTION - LH / RH     | 2           | \$                     | 32.00            | \$ 12.56           |
| 9                            | REAR BUMPER LOCKING MECHANISM           | 2           | \$                     | 59.00            | \$ 46.72           |
| 10                           | REAR BUMPER SPOILER                     |             | \$                     | 234.00           | \$ 187.20          |
| 11                           | REAR LIGHT REFLECTOR - LH / RH          | 2           | \$                     | 82.00            | \$ 32.24           |
| 12                           | LED TAIL LIGHT - LH / RH                | 2           | \$                     | 1,734.00         | \$ 1,387.20        |
| 13                           | TAIL LIGHT TRIM - LH / RH               | 2           | \$                     | 60.00            | \$ 23.36           |
| 14                           | REAR BUMPER BRACKET - LH                |             | \$                     | 27.00            | \$ 21.12           |
| 15                           | REAR BUMPER BRACKET - RH                |             | \$                     | 28.00            |                    |
| 16                           | REAR BUMPER GUIDE SECTION - LH / RH     | 2           | \$                     | 132.00           | \$ 52.16           |
| 17                           | REAR PARKING AID SENSOR - INNER / OUTER | 4           | \$                     | 968.00           |                    |
| 18                           | REAR PARKING AID SEAL RING              | 4           | \$                     | 14.00            |                    |
| 19                           | REAR BUMPER WIRING SET                  |             | \$                     | 510.00           |                    |
| 20                           | REAR CROSS PANEL                        |             | \$                     | 356.00           | \$ 284.40          |
| <b>SUB TOTAL SPARE PARTS</b> |                                         | :           | \$                     | <b>10,063.00</b> | \$ <b>6,363.12</b> |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 296 P**

| S/N PARTS DESCRIPTION       |                                   | QTY       | DAMAGED PARTS & PRICES |                     |
|-----------------------------|-----------------------------------|-----------|------------------------|---------------------|
|                             |                                   |           | S/NETT                 | REMARKS             |
|                             | <i>c/f</i>                        |           |                        | <b>\$ 6,363.12</b>  |
| 21                          | REAR CROSS PANEL REINFORCEMENT    | \$        | 725.00                 | <b>\$ 579.60</b>    |
| 22                          | REAR LID                          | \$        | 2,564.00               | <b>\$ 2,051.20</b>  |
| 23                          | REAR LID ATTACHMENT PARTS         | \$        | 291.00                 |                     |
| 24                          | REAR LID HINGE - LH / RH          | 2 \$      | 506.00                 | <b>\$ 202.40</b>    |
| 25                          | REAR LID FLAP GASKET              | \$        | 203.00                 |                     |
| 26                          | REAR LID LOCK STRIKER             | \$        | 49.00                  |                     |
| 27                          | REAR LID LOCK                     | \$        | 184.00                 |                     |
| 28                          | PACKING ADHESIVE                  | \$        | 18.00                  | <b>\$ 14.40</b>     |
| 29                          | REAR LID LOCK ACTUATOR            | \$        | 1,330.00               | <b>\$ 1,064.00</b>  |
| 30                          | AUDI EMBLEM                       | \$        | 122.00                 | <b>\$ 97.60</b>     |
| 31                          | A3 INSCRIPTION                    | \$        | 95.00                  | <b>\$ 75.36</b>     |
| 32                          | REAR LID TRIM PANEL               | \$        | 303.00                 |                     |
| 33                          | REAR CROSS PANEL TRIM             | \$        | 153.00                 |                     |
| 34                          | REAR NO PLATE                     | S/N \$    | 60.00                  |                     |
| 35                          | REAR WINDSCREEN SEALANT           | S/N \$    | 200.00                 |                     |
| 36                          | 1/4 GLASS SELANT (RHS)            | S/N \$    | 200.00                 | <b>\$ 100.00</b>    |
| 37                          | METAL FILLER POWDER               | S/N \$    | 280.00                 | <b>\$ 140.00</b>    |
| 38                          | STONE CHIP                        | S/N \$    | 180.00                 |                     |
| 39                          | CAVITY WAX                        | S/N \$    | 140.00                 | <b>\$ 140.00</b>    |
| 40                          | ACRYLIC SEALANT                   | S/N \$    | 180.00                 | <b>\$ 180.00</b>    |
| 41                          | <b>ADDED PARTS - SEE ATTACHED</b> | <b>\$</b> | <b>1,201.00</b>        | <b>\$ 990.24</b>    |
| 43                          | SUNDRIES                          | \$        | 500.00                 | <b>\$ 171.04</b>    |
| <b>TOTAL SPARE PARTS</b>    |                                   | :         | <b>\$ 19,547.00</b>    | <b>\$ 12,168.96</b> |
| <b>TOTAL LABOUR CHARGES</b> |                                   | :         | <b>\$ 25,932.00</b>    | <b>\$ 12,932.00</b> |
| <b>GRAND TOTAL</b>          |                                   | :         | <b>\$ 45,479.00</b>    | <b>\$ 25,100.96</b> |

ALL CHARGES ARE INCLUSIVE OF GST

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

## Supplementary Estimate 2

GST Reg No. 19-9902271-W

| <b>AIG Asia Pacific Insurance Pte Ltd</b><br>78 Shenton Way<br>#07-16 AIG Building<br>Singapore 079120<br><b>Attn: Mr. Adrian Ling - Motor Claims Dept</b><br><b>Tel: 6841 0055 - Fax: 6256 4315</b> |                                                                      | <b>Estimate No.</b><br><b>Date</b><br><b>Service Advisor</b><br><b>Pages</b><br><b>Regn No</b><br><b>Model No</b> | PA/OD/0777/2020/NS<br>31-Oct-20<br>George Wong<br>1<br>SMR 296 R<br>Audi A3 Sedan 1.0 TFSI |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|
| Quantity                                                                                                                                                                                             | Description                                                          | Unit Price                                                                                                        | Amount                                                                                     |
| <b><u>LABOUR</u></b>                                                                                                                                                                                 |                                                                      |                                                                                                                   |                                                                                            |
| 1                                                                                                                                                                                                    | To remove and renew rear exhaust silencer and align to position. S/N | \$ 480.00                                                                                                         | <b>\$ 480.00</b>                                                                           |
| <b><u>PART</u></b>                                                                                                                                                                                   |                                                                      |                                                                                                                   |                                                                                            |
| 1                                                                                                                                                                                                    | REAR SILENCER                                                        | \$ 677.00                                                                                                         | <b>\$ 569.60</b>                                                                           |
| 2                                                                                                                                                                                                    | REAR SILENCER DUAL CLIP                                              | \$ 55.00                                                                                                          | <b>\$ 44.96</b>                                                                            |
| 3                                                                                                                                                                                                    | REAR SILENCER EXSHAUST SYSTEM                                        | \$ 77.00                                                                                                          | <b>\$ 63.04</b>                                                                            |
| 2                                                                                                                                                                                                    | KEYLESS CONTROL UNIT                                                 | \$ 69.00                                                                                                          | <b>\$ 55.12</b>                                                                            |
| 3                                                                                                                                                                                                    | REAR WHEEL HOUSING LINER ADAPTER-RH                                  | \$ 37.00                                                                                                          | <b>\$ 29.52</b>                                                                            |
| 4                                                                                                                                                                                                    | CONNECTING PLATE-LH/RH                                               | \$ 286.00                                                                                                         | <b>\$ 228.00</b>                                                                           |
| <b>TOTAL</b>                                                                                                                                                                                         |                                                                      | <b>\$ 1,681.00</b>                                                                                                | <b>\$990.24</b>                                                                            |

For Premium Automobiles Pte Ltd

\_\_\_\_\_  
 Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT