

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

ONG KOK HSING IAN
c/o 46 Lentor Plain
Singapore 786548

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Subject to final approval from Insurance Company

Date: 17/10/2020

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: M.BENZ W126 / SBP 6575 R	
1pc	rear end panel nett	975.40 X
1pc	rear bumper nett	2,150.40 ✓
1pc	bumper chrome moulding centre nett	1,150.00 ✓
2pcs	rear bumper side chrome trim nett	970.00 ?
2pcs	rear bumper side retainer Nett	213.40 X
2pcs	rear bumper reinforcement absorber nett @ 396.50	793.00 X
2pcs	rear bumper bracket nett @ 195.00	390.00 ?
1pc	rear bumper inner pad Nett	345.00 X
1pc	rear end panel garnish Nett	645.00 X
2pcs	tail lamp assy s.n nett @ 950.00	1,900.00 ✓
	sub-total	9,532.20
	less 10%	953.22
	sub-total	8,578.98
1set	reverse sensor 4 sensor type s.nett	400.00 ✓
	To remove and replace the parts mentioned above ,panel beat and realign the necessary affected areas.	800.00 250
	To check wiring system.	80.00 20
	To apply rust proofing on affected areas.	150.00 X
	To apply waterproof sealant on affected areas.	150.00 X
	To apply putty & spray painting on affected areas.	450.00 300
	To install reverse sensors.	80.00 60
	To remove carpet , trimming to enable repair.	80.00 X
	Total	10,768.98