

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Alfred Toh

Date: 22 Oct 2020

**Preliminary Advice**

Vehicle No	: SLH8096L	Accident Date	: 12/10/2020
Make	: TOYOTA PRIUS HYBRID	Policy No.	: DMHCSNA00005762000
Assignment Date	: 16/10/2020	Excess	: S\$2,000.00
Date of Inspection	: 21/10/2020	Est. Duration of Repair	: 5
Inspection At	: ALLSWELL MOTOR TRADERS (HQ) 25 DEFU LANE 9 SINGAPORE 539266		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,486.00
Revised Amount	:S\$	8,006.00
Check Items (Estimated)	:S\$	440.00
Total	:S\$	8,446.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	37,874.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,126.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : PENDING FOR SOME PARTS PRICES.