



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10802/CHEN JIANGLIN Reg No/Reg Date SLE3489K / 25/03/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH000554 Engine No 3A92UHL8559 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/10/2020/ 09:55	QUD	247 / DonBong	58602
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, RH FRONT FENDER, FRONT BUMPER, FRONT BODY KITS, REPAIR RH FRONT DOOR, REPAIR FRONT BONNET	450.		✓	900 2475.00
E PNT88000	REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK			NN	X? 100.00
A 55900099	TOP UP A/CON GAS AND CHECK A/CON SYSTEM			NN	X? 80.00
E PNT98000	PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BUMPER, ✓ RH FRONT FENDER, FRONT BODY KITS, RH FRONT DOOR, RH FRONT FENDER FRONT BONNET AND AFFECTED PORTION	350		✓	1400. 1050 2800.00
M SUNDRY	APPLY BODY SEALANT			NN	X 80.00
A 54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM			✓	✓ 30.00
M SUNDRY	PERFORM RUST PREVENTION			NN	X 80.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST			✓	✓ 120.00
M SUNDRY	SUPPLY FRONT NUMBER PLATE WITH FRAME			NN	X 50.00
M SUNDRY	APPLY FRONT BODY KITS SEALANT			NN	X? 60 80.00
M SUNDRY	RE-APPLY BODY ZERTONA COATING ON AFFECTED PORTION			NN	X? 320.00
M SUNDRY	SUNDRIES			✓	20 50.00
M PANEL ASSY,FR END		1.00	1055.00	23.00	X 812.35
M PANEL,HEADLAMP SUPPORT,UPR		1.00	65.00	23.00	? 50.05
M CONDENSER ASSY,A/C REFRIGE		1.00	758.00	23.00	? 583.66

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include
 any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered
 after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed
 deposit of 50% of the above estimate is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10802/CHEN JIANGLIN Reg No/Reg Date SLE3489K / 25/03/201 Date In/Mileage / 0 Chassis No MMBSTA13AKH000554 Engine No 3A92UHL8559 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/10/2020/ 09:55	QUD	247 / DonBong	58602

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M PANEL,AIR GUIDE	1.00	112.00	23.00	nnx ? 86.24
M RADIATOR ASSY	1.00	967.00	23.00	nnx ? 744.59
M LLC 4L	1.00	26.00	23.00	nnx ? 20.02
M PANEL,AIR GUIDE,RH	1.00	11.00	23.00	nn x 8.47
M PANEL,AIR GUIDE,LH	1.00	11.00	23.00	nn x 8.47
M GRILLE,RADIATOR	1.00	554.00	23.00	nn x 426.58
M BRACKET,FR BUMPER,LH	1.00	13.00	23.00	nn x 10.01
M BRACKET,FR BUMPER,RH	1.00	13.00	23.00	nn x 10.01
M COVER,HEADLAMP SUPT PANEL	1.00	62.00	23.00	nn x 47.74
M GRILLE,FR UNDER	1.00	165.00	23.00	nn ? 127.05
M CLIP,FR BUMPER	10.00	4.00	23.00	nn ? 30.80
M FACE,FR BUMPER	1.00	703.00	23.00	nn ? 541.31
M GARNISH,FR BUMPER,RH	1.00	127.00	23.00	cut ? 97.79
M HEADLAMP ASSY,RH	1.00	660.00	23.00	nn ? 508.20
M LAMP ASSY,FOG,FR RH	1.00	303.00	23.00	nn ? 233.31
M SHIELD,FR WHEELHOUSE,RH	1.00	98.00	0.00	nn ? 75.46
M CLIP,FR BUMPER	10.00	4.00	23.00	nn ? 30.80
M EMBLEM ECO	1.00	17.00	00.00	nn ? 17.00
M BODY KIT, ATTRAGE	1.00	1643.00	00.00	nn ? 1643.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate

SURVEYOR NAME: Taufik 97495449

SURVEYOR SIGNATURE: [Signature]

DATE: 19/10/20 2200pm

REMARKS: Not Advise Repair

Ex: to be advise Resurvey before paint

04 days

taufik@lkk.com

Confirm & accepted by

12,880.60

7% GST on Net 12302.45 12,302.45
861.17

Total Payable 13,163.62

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that deposit of 50% of the above estimate is payable before commencement of the work. You must also agree to pay the balance of the estimate upon completion of the work.