DYNAMIC AUTOWORK PTE. LTD.

8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, S'PORE 415875 Tel: 6341 6789 Fax: 6341 6778

Co. Reg. No.: 201436361C

Date: 19/10/20	By Fax &/ Email
To:	
Attn: Motor Claims Department	
Re: Accident involving motor vehicle Nos. SJU 5777 and along Buyong Road on	
We refer to the above matter.	
We are instructed by Heng Kim Peng to notify you of a roon_15/10/2020 at about 13:45 at Buyong Road	ad traffic accident
involving our client's/customer's vehicle registration number_SJU 5777E	and vehicle
registration number SMU 1504S (your insured) at the material time.	

As a result of the accident, our client's /customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Thank You.

Yours faithfully

Abby

Hp: 9856 4815