

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

20 OCT 2020

E S T I M A T E

Estimate No. : b1 56323
Date Estimated : 19/10/2020
Prepared By : Joseph Yaguel

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Wong Bee Hua Susan
5 Siglap Road
#07-33

Singapore 448908

- ACCOUNT -

121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBV8813D	WBALX32050C952009	30/05/2012	650i/2 (A)	0

DESCRIPTION

To replace front bumper panel and left front side panel

1700 2,125.00

To respray front bumper and left front fender

1730 1,923.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).

450 531.00

To replace tyre and wheel rim including balancing. (1x).

80.1 94.00

To check electrical wiring system at the front section for proper function including adjustment of headlights.

150 177.00

To carry out body cavity preservation. (Per panel).

nn 118.00

Sundries

80 150.00

Total Labour 1: 5,118.00

DESCRIPTION

ALLOY RIM 9JX19 STY SPK 366

QTY

PRIC

VALUE

Slide element

1

1,490.05

1231.40 1,490.05

FRT LH FENDER

1

9.00

nn 9.00

Set of mount

1

1,120.75

Ry 1,120.75

FRT BUMPER CARRIER

1

33.55

NN 33.55

FRT BUMPER IMPACT ABSORBER TOP

1

783.75

nn 783.75

FRT BUMPER TRIM PRIMED (PDC)

1

68.20

nn 68.20

BMW EMBLEM

1

1,565.90

de 1,565.90

71.60

nn 71.60

Total Parts : 5,142.80

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 56323
Date Estimated : 19/10/2020
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SBV8813D	WBALX32050C952009	30/05/2012	650i/2 (A)	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 30/10/2020 Excess S\$ _____

Surveyor's Name Tayhm Sign [Signature]

Surveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tayhm@lkk.com

No. of Working Days Recommend 05 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	5,118.00
Parts	:	5,142.80
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	718.26
Grand Total	:	10,979.06

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **