



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 20.27957

Date: 29<sup>th</sup> October 2020

Our Ref: CS1/LAW20011368/Uyd3s2

**M/s AXA Insurance Pte Ltd**

c/o: Seah Ong & Partners LLP  
36 Robinson Road  
#12-03 City House  
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBA 4277M  
INSURED VEHICLE: PC 8868E ACCIDENT DATE: 15/10/2019**

We thank you for your instruction on 19/10/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBA 4277M from M/s Constant Appraiser Services.
- b) Survey report by Autoprobe Consultants with colour photographs.
- c) Final Repair Bill of GBA 4277M from M/s Choo Motor Spray Painter.
- d) Singapore Accident Statement of Vehicles GBA 4277M and PC 8868E.
- e) Colour damaged vehicle photographs of GBA 4277M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

|                      |                        |
|----------------------|------------------------|
| Registration Number  | : GBA 4277M            |
| Make & Model         | : Opel Combo-C 1.3 DTJ |
| Year of Registration | : 2007                 |
| Chassis Number       | : W0L0XCF2574306606    |
| Engine Capacity      | : 1248 cc              |

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.