

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD530X

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

20 OCT 2020

AAD2010-078

*Not Notified**Recovery B4 paint***SHD530X**

VF1ABL15AUC283495

RENAULT

LATITUDE

19/10/2020

AIG

24/11/2017

	PART
1	BUMPER COVER FRT
1	BUMPER SPOILER FRT
1	BUMPER RETAINER FRT LH
1	HEADLAMP LH
1	HEADLAMP PANEL FRT LH
1	BUMPER FOG LAMP GRILLE LH
1	FENDER PANEL FRT LH
1	WHEELARCH FRT LH
1	AIR CLEANER BOX
1	AIR CLEANER HOSE
1	AIR CLEANER LOWER
1	DOOR PANEL FRT LH
1	DOOR WAIST SEAL OUTER FRT LH
1	DOOR MIRROR LH

	LIST	
\$	Bu / mfg	747.20 ✓
\$	Sm	344.70 X
\$	Dis	101.40 ✓
\$	Cr	743.60 ✓
\$	R	128.30 X
\$	Sm	207.21 X
\$	B	437.10 ✓
\$	Sm	191.40 X
\$	Sm	464.20 X
\$	Sm	175.85 X
\$	Sm	271.26 X
\$	B	2,844.66 ✓
\$	Sm	92.20 X
\$	Sm	1,483.40 X
TOTAL	\$	8,232.48
10%	\$	823.25
	\$	7,409.23

	Special Nett
1	BUMPER CLIP FRT
1	BUMPER RETAINER CLIP FRT
1	WHEELARCH CLIP FRT
1	FRONT DOOR STICKER "Trans-Cab"
1	FRONT DOOR STICKER "Classic"

\$	Na	90.00	605N
\$	na	75.00	X
\$	na	75.00	X
\$	Na	80.00	605N
\$	Na	80.00	155N
TOTAL	\$	400.00	

TOTAL PARTS \$ 7,809.23

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD530X

AAD2010-078

LABOUR

To rust-proofing and apply undercoat of the affected areas.	\$	230.00	601
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	601
Putty and spray painting of the affected portion.	\$	1,400.00	6601
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	1,400.00	5001
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
TOTAL	\$	3,760.00	
Over All Total	\$	11,569.23	

(PART-BY-PART) Repair Days~~10 Days~~
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: